CHILTON'S

MOTORAGE

December, 1957

merry christmas



You can make this claim with Sealed Power KromeX Piston Ring Sets

When you install KromeX, you're giving your customer the world's best ring job because KromeX sets have Sealed Power's new stainless steel oil ring (U.S. Pat. No. 2,789,872). The performance record of this ring is so phenomenal America's two largest auto manufacturers have adopted it as standard original equipment.

Replacement Record Equally Astounding In replacement service mechanics and fleet owners have discovered just as astonishing results. KromeX ring sets with the stainless steel oil ring positively control oil even in tapered or out of round cylinders—positively control smoking under deceleration. The oil ring will not sludge or corrode because of the stainless steel finish. And it has chrome-plated steel side rails for more than double normal ring life. These rails seat instantly. Available in Sealed Power KromeX ring sets for engines which require super oil ring performance.

SEALED POWER CORPORATION . MUSKEGON, MICHIGAN

Sealed Power KromeX Ring Sets

THERE'S A PERMATEX PRODUCT FOR EVERY MAINTENANCE NEED



SEALING COMPOUNDS

Form-A-Gasket No. 1 Form-A-Gasket No. 2 Form-A-Gasket No. 3 Super '300" Form-A-Gasket Pipe Joint Compound No. 51







SEALANT-CEMENTS

Stick-N-Seal **Gasket Cement** Glass Sealer Indian Head Gasket Shellac Compound









SHOP REPAIR ITEMS

Valve Grinding Compound Prussian Blue





OILS & LUBRICANTS

Penetrating Oil Solvo Rust Toon-Oyl Anti-Seize Compound Indian Head Clear Rubber Lubricant











POLISHES & CLEANERS

Blue-Blazes Silicone Cleaner-Polish Perma-Lustre Cleaner-Polish Acrylic Cleaner & Polish Taroff Car Wash **Fabric Cleaner** Windshield Cleaner Concentrate **Chromium Polish**





COOLING SYSTEM PRODUCTS

Block & Head Sealer Cooling System Cleaner & Conditioner Water Pump Lubricant & Radiator Anti-Rust **Heavy-Duty Radiator Cleaner** Radiator Sealer (liquid) **Double Action Radiator Cement** Indian Head Radiator Ceigent







HYDRAULIC FLUIDS

Knee Action-Jack-Shock Absorber Oil Hydraulic Jack Oil Heavy Duty Brake Fluid Moderate Duty Brake Fluid Automatic Transmission Fluid (Type A) **Hudson Clutch Fluid** Indian Head Hydraulic Brake Fluid









PERMATEX COMPANY, INC. General Offices: 300 Broadway, Huntington Station, N.Y.

Factories: Brooklyn 35, N.Y. Kanese City 15, Kanese

Factories: Brooklyn 35, N. Y., Kansas City 15, Kans.




MONEY-MAKING CARBURETOR TUNE-UPS IN A JIFFY

Save time, prevent mistakes, make more money on every job, with HYGRADE'S convenient JIFFY KITS.

JIFFY-RAKS ARE FREE

Ask your jobber about JIFFY KITS in balanced JIFFY-RAK Merchandising assortments. It's the handy way to keep your kits. You pay only for the kits.



Want details in a jiffy? Call your jobber today, or write HYGRADE PRODUCTS DIVISION, Standard Motor Products, Inc., Long Island City 1, N. Y.



JUST THE PARTS YOU NEED IN A JIFFY! Gaskets, pump pistons, needles and seats, extra parts where necessary, complete instructions for each kit, and even the gauges you need for the job! All in one compact package. It's economical. (You only pay for the parts you always use.) You'll want JIFFY KITS for every make and model car.

HYGRADE Jiffy Kit

carburetor tune-ups in a jiffy!

Chilton's MOTOR AGE, DECEMBER, 1957

CHILTON'S

MOTOR AGE

WITH WHICH IS COMBINED AUTOMOBILE TRADE JOURNAL

FRANK P. TIGHE, Editor

WM. H. WOLFE, Managing Editor • JOHN K. MONTGOMERY, Technical Editor • WM. M. MONTGOMERY, Associate Editor • JOHN B. LAWRENCE, Associate Editor • MARCUS AINSWORTH, Statistical Editor • HOWARD KOHL-BRENNER, Art Director • MURRAY SIMKINS, Chief Detroit News Bureau • EDWARD JANICKI, Detroit News Editor JOSEPH GESCHELIN, Engineering Editor • KEN ROSE, Midwest Editor • GEORGE H. BAKER, RAY M. STROUPE, NEIL REGEIMBAL, Washington News Editors • PAUL WOOTON, Washington Member of the Editorial Board

DECEMBER 1957

Vol. 77, No. 1

IN THIS ISSUE


NEWS	Report to Our Readers	31
	Newscoop	33
	On the Go with IGO	72
ARTICLES		
	A Flush and a Full House	37
	Be Sure the Pressure Cap Works	40
	Studebaker Trucks Offer Four Engines	42
	Dodge Heavy Trucks get Automatic Shifts	43
	Chevy Adds 12 New Trucks	44
	Ford Trucks Offers Variety of Models	45
	New V-8 Engine for GMC Trucks	46
	Horsepower, Torque Ratings for '58	48
	Philly Show Welcomes 125,000	50
	Motor Age Index for 1957	53
	Trouble Shooting Electric Window Lifts	62
DEPARTMENTS	Service Man's Idea Book	52
	Body Shop Tips	56
	Service Suggestions	57
	Readers' Clearing House	58
	New Products	60
	Tune-Up Specifications	64
	New Car Registrations	64
	Price, Weight and Body Table	67
	Shop Kinks	68
	Calendar of Coming Events	92
	Advertisers' Index	94
	Last Laugh	94



MOTOR AGE. Published monthly by Chilton Company, Chestnut & Fifty-sixth Streets, Philadelphia 39, Pa. Entered as Second Class Matter December 27, 1835, at the Post Office at Philadelphia, Pa.; under the Act of Congress of March 3, 1878. Subscription price: United States, United States Fossessions, \$4.09 for one year; \$7.00 for two years. Canadian, Prorigin \$5.00 per year; \$5.00 for two years at the Congress of Congress of



TAKE ROCHESTER CARBURETOR TRAINING FREE AND "SIGN UP" FOR MORE JOBS . . . MORE PROFITS!




So sign up now! Write to Service Department, United Motors Service Division, General Motors Corporation, General Motors Building, Detroit 2, Michigan.



ROCHESTER PRODUCTS DIVISION OF GENERAL MOTORS, ROCHESTER, N. Y. Specified as original equipment on more new cars than any other carburetor







says CLIFFORD O. GLEDHILL
Courtesy Motors, Inc., Salt Lake City

"Our sales are not restricted to a certain area, so we need a finance set-up that can handle customers efficiently no matter where they live or where they move—in state or out. The nationwide offices of Commercial Credit do a thorough job of handling all our financing needs. We're free to concentrate on sales and service. We shopped around before selecting Commercial Credit Plan four years ago and found it's the best for both the dealer and his customer. No matter what phase of their operation you pick, whether wholesale financing, the finance reserve, or complete dealer control of financing, Commercial Credit is tops."

Commercial Credit dealers are <u>successful</u> dealers

Write or call our nearest office for complete information on the benefits of COMMERCIAL CREDIT PLAN. Why not do it today?



A service offered through subsidiaries of the Commercial Credit Company, Baltimore . . . Capital and Surplus over \$200,000,000 . . . offices in principal cities of the United States and Canada.

Precision Bearings . . . PLUS!



There's more here for you than meets the eye...

The red-and-black Federal-Mogul package contains a lot more than bearings! Invisible, but highly valuable to you, are the service aids available through your jobber. Federal-Mogul provides literature and manuals containing specific installation information. He also has

special bearing service tools that will make your job go more easily, quickly and surely. This assistance is always ready for you—it was designed to help you toward better bearing service. Ask your Federal-Mogul Jobber!


FEDERAL-MOGUL SERVICE

DIVISION OF FEDERAL-MOGUL-BOWER BEARINGS, INC. DETROIT 13, MICHIGAN





RESEARCH . DESIGN . METALLURGY . PRECISION MANUFACTURING . SERVICE



Primer-Surfacer sanding race shows how to get jobs out faster with less labor!

To save costly shop time, test the sanding speed of your primer-surfacer. You'll get fast, easy sanding with no tearing or pulling when you use High Speed "Duco" Primer-Surfacer. It actually gives the fastest sanding that can be obtained without sacrificing other important features. And what are these other features? Fast filling, fast drying, plus a beautiful color holdout for high gloss with less rubbing. You'd save with High Speed "Duco" Primer-Surfacer even if it cost more. But since it reduces 2 to 1 (1 gal. gives 3 at the gun), it costs less than many so-called "bargain" primers. You save money with High Speed "Duco" Primer-Surfacer every time!

Fast-drying Easy-sanding Money-saving

"DUCO" LACQUER HIGH SPEED PRIMER-SURFACER

DU PONT REFINISHING MATERIALS



BETTER THINGS FOR BETTER LIVING

Announcing—A new Series and tester to help you make more

MORE EFFICIENT CLEANING MORE ACCURATE TESTING A LESS SERVICING TIME A DOES YOUR SELLING FOR YOU

SERIES "800" UNIT FEATURES

- Compressed air inlet-1/2" pipe thread-male Double-action valve for cleaning and dusting
- Tester button switch



"800" Champion spark plug cleaner money—in less time!

Dealers who have sales-tested the new "800" series Champion service unit call it the greatest merchandising aid in spark plug history!

This new Champion unit has 4 big advantages over any other spark plug cleaning and testing equipment: better cleaning, more accurate testing, faster servicing—and a "built-in salesman" that does your selling for you.

Champion's new "800" service unit helps you make more money on spark plug service because it helps you do a better job in less time. A new filter keeps all dust and dirt out of the cleaning abrasive . . . assures you fast, efficient, even cleaning of every plug.

The "built-in salesman"—a new type of sparking-indicator gauge—shows directly if an old plug should be replaced. It eliminates the bother (and possible inaccuracy) of checking the old plug against a new one. This new gauge measures a plug against a fixed standard. Your customer can see for himself if new Champions are needed. This

easy-to-understand gauge makes your salestalk for you.

You don't have to sell the new plugs—you just install them.

There are real profits to be made from spark plug sales and service. And this advanced Champion cleaner and tester can help you make more money—in less time—and with less effort. Your new "800" service unit can be the biggest profit-maker in your service department—and your cost is only \$64.50 for the bench model, \$67.50 for the floor model. Order yours from your Champion supplier—today.





NEW DOUBLE-FILTER CLEANER BAG—separates dirt and dust from cleaning abrasive—faster, more dust-free cleaning action—simple to service.



NEW SPARKING-INDICATOR TESTER DIAL—a new, simpler method of testing spark plugs—single plug test saves time—sells new Champions fast.



HEAVY-DUTY WATER TRAP—now standard equipment—keeps abrasive compound free from air-line moisture —protects air lines, etc. from rust.



WEED CHAINS ARE MONEY IN THE BANK WHEN BLIZZARDS COME!


Unless it just stops snowing in these United States, tire chains are one of your safest winter investments. One good snow and out they go—we've yet to see anything else that can do the job WEED V-Bar chains can in really bad weather. So stock up—take care of your regular customers and keep an eye on the profits at the same time. Sell WEEDS—the people know them.





American Chain & Cable Company, Inc., York, Pa., and Bridgeport, Conn. • In Canada: Dominion Chain Company, Ltd., Niagara Falls, Ont.

In Business for Your Safety



MoPar mufflers add extra miles built for today's powerful gas surges

Sell your service to your customers: be sure they understand the need for a quality muffler, built for today's more powerful, high-compression engines.

And be sure they understand these major advantages of the MoPar muffler:

- engineered by Chrysler Corporation for Chrysler Corporation vehicles
- top rigidity and longer life
- extra strength, less vibration
- quick operation
- greatest safety protection
- less back pressure

You'll be helping yourself by making the most of those MoPar sales points. You'll sell more mufflers—and you'll make and keep loyal, satisfied customers.

MoPar mufflers are official, authentic Chrysler Corporation products. Order from your MoPar wholesaler salesman or your Plymouth, Dodge, De Soto, Chrysler or Imperial dealer now.



MOPAR DIVISION > CHRYSLER MOTORS CORPORATION
DETROIT 31, MICHIGAN

24-HOUR SERVICE on Pittsburgh Safety Glass

There's no need to carry large inventories of automotive safety glass when you order glass through Pittsburgh Plate's Depot System. No matter what type of automotive glass you must replace, you can easily get it from your nearest Pittsburgh Plate Branch or Warehouse on 24 hours' notice.

Don't crowd your shop . . . don't carry large inventories, trying to anticipate your Safety Glass replacement jobs. Let us be your warehouse. When you have a replacement job, call Pittsburgh Plate. In 24 hours or less, the exact

piece of glass you need will be in your shop. Your job will be finished and your customer on his way, completely satisfied.


Pittsburgh Plate's Depot System gives you 24-hour service on all types of Safety Glass, Curved or Flat, Clear or Solex*, in Duplate* Safety Plate Glass, Duolite* Safety Window Glass or Herculite* Tempered Plate Glass. For full information, contact your nearest Pittsburgh Branch or Distributor, Pittsburgh Plate Glass Company, 632 Fort Duquesne Blvd., Pittsburgh 22, Pa.



Paints · Glass · Chemicals · Brushes · Plastics · Fiber Glass

PITTSBURGH PLATE GLASS COMPANY

In Canada: Canadian Pittsburgh Industries Limited



THOMPSON PRODUCTS

"the original equipment line"

ENGINE AND CHASSIS PARTS FOR CARS, TRUCKS, TRACTORS, BUSES

● For over half a century Thompson has been known as "the original equipment line". Every well-known manufacturer of cars, trucks, tractors, buses—even aircraft—uses Thompson parts as original equipment. That's because they know that Thompson parts are reliable parts.

Repairmen and servicemen, too, must stake their reputations to a large degree on the quality and serviceability of the replacement parts they install. Poor fitting, poor performing parts cost you labor, cost you money, cost you customers.

Protect your business by always installing precision made Thompson parts. Do as the automotive manufacturers do. Rely on Thompson engine and chassis parts—"the original equipment line".



PROGRESSIVE ENGINEERING MAKES THE DIFFERENCE

CONTACT **ADJUSTING** SCREW WELDED MOLDED SOFT MOLDED NYLON RUBBER GASKET

REGULATORS GIVE IMPROVED ALL-WEATHER PERFORMANCE

Better electrical performance and greater dependability in any weather are important user benefits found in Delco-Remy's waterproof standard generator regulators, now available for general replacement use.

And here are the features that make them the *right* regulators for millions of Delco-Remy equipped cars and trucks.

- New overhanging one-piece formed-steel cover and mating base shed road splash . . . convenient attaching screws are *outside* the enclosed area. Molded soft rubber gasket seals out harmful oil and water vapors.
- Integral sleeves of molded nylon insulator form permanent seal around rivets—assure watertight base.
- New, longer, more flexible armature contact spring on voltage regulator unit assures more positive closing of contact points for smoother operation.
- Welded electrical connections, and highest quality tungsten and non-tarnishing precious metal contact points, assure minimum resistance, maximum durability.
- Special fine thread screw-type controls allow easy, highly accurate adjustment of all three units.

Always replace with Delco-Remy waterproof regulators when you service Delco-Remy equipped cars and trucks. These improved regulators, built to highest quality standards by the original equipment manufacturer, are available from your car or truck dealer or the United Motors System.

DELCO-REMY . DIVISION OF GENERAL MOTORS . ANDERSON, INDIANA



GENERAL MOTORS LEADS THE WAY-STARTING WITH

Delco-Remy

ELECTRICAL SYSTEMS



No question about the right way to start customers off to a smooth-driving future—sell them Quaker State! It's the years-ahead, Pure Pennsylvania Motor Oil, best for high compression engines and great for business. Satisfaction by the quart!

SERVICE EQUIPMENT



will help you get more business into your shop... and more profit out of it!

You don't need to aild any space ... nor add any men ... to get a greater share of the automotive service business ... Simply add modern Weaver Equipment to enable your shop to profitably handle the services you have been passing up.

As pioneers, and the largest manufacturer of major service equipment. Weaver will help you. Detailed service manuals and instruction sheets are supplied right along with equipment.

Here's the deal where everybody benefits. When this modern equipment is used, work can be turned out faster, with less effort, — and more jobs can be completed each day . . . Mechanics can make more money . . . Service Department can make more profit . . . And, customers set emicker and better tervice.

All 28 major items of Weaver equipment are AVAILABLE on EASY TIME PAYMENTS

---> See next 3 pages -->

WEAVER

MOST COMPLETE LINE OF MAJOR



DeLuxe
"Twin Post"
Lift Wheel
Alignment Outfit



Twin Post Lifts Available in 8 models to handle all vehicles



"Rack Type" Alignment Outfits For all passenger cars



Single Post Frame Type Lifts For all passenger cars



"Floor Level"
Alignment Outfits
For locations where
floor space is limited



Single Post Lifts Available either "free-wheel" rail type or "roll-on" type



3-Way Alignment Gauges For faster, easier wheel alignment service



Triple Post Lift For servicing heavy tractor-trailer units



Tru-Way
Toe Gauges
For fastest, accurate
method of checking
"toe"



established 1910

oldest and largest manufacturer of

AUTOMOTIVE SERVICE EQUIPMENT

Wheel Counterbalancers Make accurate dynamic balance in few moments



Lo-Hi-Draulic Jacks In 2, 4, 10 and 20 ton capacities



Dynamic Wheel Tester Instantly shows need for wheel balancing



Wheel Dollys Available in 3 models to answer every need



Unit Lift
For removing
transmissions,
drive shafts, etc.



Hydraulic Bumper Lifts With exclusive foot operation



Car Washers Adaptable to all type operations



Mechanical Bumper Jacks For lifting passenger cars by bumpers Hydraulic Hand Jacks For under-axle use. In 1½, 3, 5, 8, 12 and

20-ton capacities



Wash Rack Jacks Specially designed for speeding wheel washing



Service Stands in 5, 10 and 14 tons capacity.



WEAVER

established 1910 · oldest and largest manufacturer of

MOST COMPLETE LINE OF MAJOR AUTOMOTIVE SERVICE EQUIPMENT

Brake Testers Available in 5 models to handle every load requirement



Photoscope Headlight Testers Come in portable and track type

Rayoscope
Headlight Testers
(Extreme Right)
In portable and
track types



Combination
Brake and
Alignment Testers

Come in 3 models to meet varied requirements



Electric Eye Headlight Testers 3 models, portable and track types



Wheel Alignment

Testers
Made in
4 models,
surface and flush types



Air Compressors 45 models to choose from



CLIP and MAIL COUPON for FREE CATALOGS

WEAVER MANUFACTURING CO., SPRINGFIELD, ILLINOIS, U.S.A.

Please send free descriptive literature and details on the following

Weaver items:

AME....

FIRM NAME

STREET ADDRESS_____

CITY____ZONE__STATE___



WEAVER MANUFACTURING CO. Springfield, Illinois, U.S.A.

Have oil seals when you need them!





He has complete stocks of top quality, original-equipment National Seals—fills almost all orders instantly. On "odd-ball" or very old numbers, he's backed up by a nearby Federal-Mogul warehouse. He won't tell you "we'll order from the factory—10 days!" He'll say "tomorrow at the latest!" CALL HIM FOR YOUR SEAL AND BEARING NEEDS!

2. Install a National Seal Service Stock



Your National jobber will gladly—and quickly—install a fast-turnover National Seal stock in your own shop. He maintains it; no work for you. You have popular seals when, where you need them. Two stocks—one holds over 100 front and rear wheel seals, the other, about 50 front wheel seals. Free cabinet, world's easiest price and interchange information.

America's largest selling replacement seal—approved original equipment on cars, trucks, buses and off-highway vehicles.

FEDERAL-MOGUL SERVICE

Division of Federal-Mogul-Bower Bearings, Inc. Detroit 13, Michigan

4400



AC announces new flexible gasoline line assortment with merchandising rack



FM-33 Merchandiser Assortmen

Assortment covers:

CADILLAC • CHEVROLET • BUICK **OLDSMOBILE • PONTIAC** and practically all other American cars

YOUR COST... \$1536

Your profit on sales of lines... 10^{22}

Includes 15 fast moving types-21 lines in all plus this attractive wall rack FREE!

Another fine assist for you from AC . . . the FM-33 Merchandiser Assortment which covers the bulk of the market and includes a handy, handsome wall rack for line storage.

The sturdy, steel rack, finished in attractive, high-luster AC colors, provides easy-access storage for the 21 AC Gasoline Lines included in the assortment, plus additional storage slots for other lines.

CALL YOUR REGULAR



Watch Walt Disney Studios' ZORRO every week on ABC-TV



AC THE ELECTRONICS DIVISION OF GENERAL MOTORS

F THE MONTH!

DEALERS

AC presents the new eight-pack spark plug display cabinet at only \$460



- COMPACT ORNAMENTAL
- Heavy, Clear Plastic Door Built-in Hasp for Padlock For Shelf or Counter . Piano-Type Hinging . Heavy Steel Construction . Shipping Weight 12-lbs.
- · Finished in Blue, Red and White

Here's just what you need for spectacular display of the new AC Eight-Packs. This handsome, ruggedly built, heavygauge steel cabinet, with transparent plastic door, holds 36 Eight-Packs-a total of 288 AC Spark Plugs.

Easy to check stock

The attractive heavy transparent plastic door makes quick stock checking easy. Packages are always neat, clean-and there when authorized personnel need them. The door is pianohinged at bottom, strongly overlaps the steel cabinet sides, and has hasp equipment for padlocking. Door is decorated with colorful embossed plug and flash design.

Holds 36 Eight-Packs

(a total of 288 plugs)

This cabinet fits easily on shelf or counter, has generous capacity, includes clip-slot under top for AC Spark Plug Applications Chart, sent with cabinet.

It's a selling display piece, too. On the top, as shown, is a foldup steel message plate identifying and selling the product. Ask your AC Supplier about this low-cost cabinet.

ORDER YOURS NOW FROM YOUR





AG SELLING SLANTS

MONEY-MAKING FACTS



NOW you can test and sell new AC Air Cleaner Elements with the flip of a switch!

The paper air cleaner market potential is growing daily by leaps and bounds. More than 40% of all 1957 cars are so equipped and many of these paper air cleaners already need replacement.

The new Model M, AC Air Cleaner Tester is your answer. With the flip of a switch, you can demon-

strate to the customer how clogged air cleaners reduce air passage efficiency and increase operating costs.

Another important point: this new tester is completely portable; use it anywhere ... service area... pump island... or in the lube bay.

Pays for itself quickly!

A recommended fifty cent service charge for testing elements—an average profit of \$1.70 per element sold—lets you recover the \$39.95 cost of this equipment in a hurry! In fact, it pays for itself many times over, making sales on its own, by giving a buyer visual proof of need. Order yours at once from your AC supplier.

SPECIFICATIONS—AC Air Cleaner, Model M—29" high, base, 23½" in diameter. Plugs into any conventional 110-volt AC outlet.

No air compressor required. Rugged metal construction with easy-to-read, calibrated scale. Shows whether element is clean, partially clogged or needs immediate replacement.

Shipping weight 26-lbs.

ORDER TODAY FROM YOUR



OF THE MONTH!

OR DEALERS

Two big reasons why ...

Profit-minded dealers everywhere now sell AC Filler Caps



SUPPLIER

TESTS ALL PRESSURE CAPS COOLING SYSTEMS

FM-19 Tester

2. THE AC CABINET MERCHANDISER ASSORTMENT

Just what the doctor ordered for the average service station . . . a husky, all-steel cabinet in handsome AC red and blue colors, to keep your cap stocks organized and available. Plus . . . an assortment of 57 fast moving, high quality AC Radiator Pressure and Gasoline Caps, 17 types in all, that cover most of the market.

Your cost for the complete deal \$3133

Your Profit on the sale of the caps _ \$1497

cooling system a complete check.

1. THE AC PRESSURE CAP AND COOLING SYSTEM TESTER

Faulty cooling systems and "tired" pressure caps that can't hold their rated pressures often contribute to poor engine performance. Unfortunately, many times, your brand of gasoline might get the blame.

That's one reason why AC developed this low cost tester . . . to help you locate and quickly correct cooling-system troubles. Dealers say the AC Tester is one of the best \$10 investments they've ever made.

And here's a seasonal tip. Now's the smart time to buy your AC Tester, because the only sure way you can guarantee your customers' all winter anti-freeze protection is to give every



LOOK AT THESE FEATURES!

- All-Steel Construction
- Eye-Catching Colors
- Lots of Room for **Additional Caps**
- Specification Chart on Reverse Side of **Display Panel**

CALL YOUR REGULAR



SUPPLIER TODAY!

FM-13 Merchandiser

Watch Walt Disney Studios' ZORRO every week on ABC-TV



THE ELECTRONICS DIVISION OF GENERAL MOTORS

"There <u>is</u> a difference in





brands of brake fluid..."

Wagner Lockheed BRAKE FLUID

is better because it's balanced!

YOU GAIN-and your customers gain-when you supply genuine Wagner Lockheed Brake Fluid...There's none better... None safer.

This top-quality fluid surpasses S.A.E.* specifications. It is compounded of the finest ingredients, and it is chemically balanced to permit it to withstand sub-zero temperatures without solidifying... to withstand extreme heat (generated from high-speed stops and hard usage) without gassing.

Also, because it is properly balanced chemically—Wagner Lockheed Brake Fluid does not cause formation of gummy residue, swelling of rubber parts, or cause corrosion of metal parts in the system...It does absorb a necessary amount of moisture, and does function properly under all operating conditions.

Wagner Lockheed Fluids answer all service needs. 21-B is for trucks, buses and cars where heavy-duty type fluid is recommended or required by state law. When ordering, specify genuine Wagner Lockheed—the brand that has been the leader for 33 consecutive years... Available in 12 oz., quart, gallon, 5 gallon, and 54 gallon containers.



YOU can depend upon Wagner Quality because Wagner Products are used as original equipment by car, bus, truck and trailer manufacturers.

CLIP and MAIL COUPON for details, and for FREE copy of valuable Bulletin HU-411 on Hydraulic Brake Servicing.

*Society of Automotive Engineers.

Wagner Electric Corporation H57-2 6498 Plymouth Ave. • St. Louis 14, Me. 6498 Plymouth Ave. • St. Louis 16, Me. 10 St. Louis 10 Canada)
6498 Plymouth Ave. (Branches in principal cities in U. S. and in Canada) (Branches in principal cities in U. S. and in Canada)
ease send us Bulletin HU-411 on Hydrosom. (e understand that there is no charge or obligation.
IAME
ADDRESS
CITY & STATE
-





Joe sure has a way with cars


with customers too...
Joe uses Timken®
bearings for
replacement!

You can be a winner every time with your customers. When they need a tapered roller bearing, install a Timken bearing. And tell 'em it's Timken. It's a name that always wins . . . a name that means quality—America's best-known bearing. When you say "Timken" you tell 'em you use the best in replacement parts. The Timken Roller Bearing Company, Canton 6, Ohio. Canadian plant: St. Thomas, Ontario. Cable address: "TIMROSCO".



CUSTOMERS LOVE YOU WHEN YOU REPLACE WITH AMERICA'S BEST-KNOWN BEARING...JUST TELL 'EM IT'S...

TIMKEN
TRADE-MARK REG. U. S. PAT. OFF.
TAPERED ROLLER BEARINGS





"Changing to Texaco brought me real money"

6 reasons why you can make money as a Texaco Dealer!

THE BEST petroleum products, known and accepted by car owners in all 48 states. Continuous research and development insure that Texaco will always have outstanding products.

THE BEST and biggest national advertising program . . . constantly *selling* Texaco Dealers to car owners everywhere.

THE BEST point-of-sale promotion material to help bring customers in and bring them back!

THE BEST customer credit card—in fact, the *only* petroleum credit card honored under *one* sign in all $48 \text{ states} \dots$ and in Canada, too.

THE BEST retailer policy—Texaco doesn't compete with its dealers . . . cooperates with them in promoting their sales of nationally advertised and accepted TBA products.

THE BEST opportunity to cash in on "touring" business—because motorists know they can get famous Texaco products wherever they drive.

WRITE OR PHONE TODAY if you'd like to be your own boss—a Texaco Dealer. Let's talk it over. No obligation. Get in touch with the Texaco Division Office nearest you.

says Charles K. Stowers, successful Texaco Dealer in Dallas, Texas.

"I tried one dealership, then changed to another, but never made any real money until I changed to Texaco in 1939. I was selling 2,900 gallons a month then. I've grown steadily. Now I am doing 50,000 gallons and expect to reach 65,000 gallons a month by the end of the year.

"I've found that any help you ask from Texaco — within reason — you'll get. That's how Texaco keeps its large, national Dealer Family together — with more take-home money.

"To any ambitious man who has the opportunity to get a Texaco dealership and be his own boss, I say, better take it!"

THE TEXAS COMPANY

DIVISION OFFICES: Atlanta, Ga.; Boston 16, Mass.; Buffalo 9, N. Y.; Butte, Mont.; Chicago 4, Ill.; Dallas 2, Tex.; Denver 3, Colo.; Houston 2, Tex.; Indianapolis 1, Ind.; Los Angeles 15, Calif.; Minneapolis 3, Minn.; New Orleans 16, La.; New York 17, N. Y.; Norfolk 2, Va.; Seattle 1, Wash.



REPORT TO OUR READERS

RUSSELL W. CASE, JR., Publisher

Charles W. Hevner, Asst. to Publisher Kip Howe, Advertising Director E. H. Miller, Advertising Manager E. W. Hevner, Circulation Manager Joseph P. Jennings, Research Manager

> Address Mail to Motor Age Chestnut & 56th Sts., Phila. 39, Pa. Phone: SHerwood 8-2000

REGIONAL MANAGERS

CHICAGO I, ILLINOIS

Suite 418 360 North Michigan Ave. Phone RAndolph 6-2166

CLEVELAND 15, OHIO

Ben E. Ball-Duane Jones 930 B. F. Keith Bldg. Euclid Ave. and E. 17th St. Phone SUperior 1-2860

DALLAS I, TEXAS

William J. Smyth 909 Mercantile Securities Bldg. Phone Riverside 7-1732

DETROIT 2, MICHIGAN

Philip Streich—Duane Jones 1015 Stephenson Bldg. Phone TRinity 5-2090

LOS ANGELES 57, CALIF.

L. H. Jackson 198 S. Alvarado St. Phone DUnkirk 7-4337

NEW YORK 17, N. Y.

Edwin H. Shaffer

100 E. 42nd St. Phone OXford 7-3400

SAN FRANCISCO 3, CALIF.

Frank W. McKenzie 1355 Market St.

Phone UNderhill 1-9737

WASHINGTON EDITORIAL OFFICE National Press Bldg., Washington 4, D.C.

> One of the Publications Owned by

CHILTON COMPANY

Executive Offices Chestnut & 56th Sts. Philadelphia 39, Pa., U.S.A.

Officers and Directors

JOSEPH S. HILDRETH, Chairman of the Board G. C. BUZBY, President

Vice Presidents

P. M. FAHRENDORF
L. V. ROWLANDS

ROBERT E. MCKENNA

WILLIAM H. VALLAR, Treasurer

JOHN BLATE MOFFETT, Secretary

MAURICE E. COX

FRANK P. TIGHE

RUSSELL W. CASE, JE. HARRY V. DUFFY GEORGE T. HOOK JOHN C. HILDRETH, JR.

STANLEY APPLEBY, Comptroller

That You May Inherit a Blessing

YOUR loyalty, as a reader of MOTOR AGE, is something that is deeply and humbly appreciated by the editors of this magazine. Loyalty is without price. It fires the writers' imagination and inspires them to do a constantly better job-for you.

This is a time for good wishes—and ours is that you may inherit a blessing. The blessing of good business and fair

Since Motor Age is and continually strives to be an important shop tool-we are pleased to tell you that something is about to happen. This shop tool of yours is being enlarged and improved to help you through a prosperous 1958.

That event takes place with the January, 1958, ASIdeas (Automotive Service Ideas) issue. We're up to our ears in plans, pictures, paragraphs and punch lines. Nothing's too good for our readers, is our motto. Watch for the "new" MOTOR AGE in January and thereafter. It will help you in your profit strategy all year long.

How to Win at Indianapolis

THE late Joe Dawson, old-time winner at Indianapolis was guest speaker at an affair in his honor, shortly after he became a National hero, at Indianapolis. Earl Mylecraine, of Atlantic Refining, was toastmaster. He hailed old Joe with great gusto and said, "Now, Joe, will tell us how to win at Indianapolis!" Joe got up and the following is his entire speech: "How to win at Indianapolis? That's simple. You come in first."

To You and Yours

IN the true spirit of the Christmas season we, the men of MOTOR AGE, extend to you and yours the sincerest wishes for a happy and holy holiday season.

Faithfully yours,

Frank Je



of course I use Pedrick Formflex rings

what else? Formflex Chrome rings are the "key" to the "new car" pep and efficiency your customers want in their car engines. Pedrick's exclusive "Equalizer" provides equal pressure everywhere around the rails for the utmost conformability and a more perfect seal. Result: quickly restored power, new oil and gas economy, much longer life, more satisfied customers.





WILKENING MANUFACTURING CO., Phila. 42, Pa. IN CANADA: Wilkening Mfg. Co. (Canada), Ltd., Toronto

Mister

JOBBER EXECUTIVE

A condensation of key items of the Jobber field is shown below. At a glance you can keep up-to-date on important events, speeches and trade conventions

• UNIFICATION APPARENT? As Motor Age goes to press word flashed that National Standard Parts Association's executive committee and board of directors have approved Aug. 14 recommendations of MEWA Reorganization Committee and NSPA Unification Committee.

Joint recommendation as originally worded carried in September's Motor Age, called for a "consideration of the board of director's of each of the respective association's in the interest of the industry as a whole, (that) a new association be formed under a new name."

Aug. 14 resolution provided for review by the respective boards of MEWA and NSPA of the proposal for unification. If boards approved, same plan to be put before the memberships of NSPA and MEWA for subsequent ratification.

MEWA's Board approved the "broad outline" of plan. Authorized establishment of \$25,000 to initially finance reorganization of associations.

• '58 PACIFIC AUTOMOTIVE SHOW—Reports on the Pacific Automotive Show, to be held in Los Angeles at the Pan Pacific Auditorium on Feb. 20-23, indicate that this event will be one of the largest ever held.

More than 350 manufacturers of parts, equipment, accessories, chemicals and allied lines drew for exhibit space in the Show. With the NSPA and the MEWA holding their Annual Conventions during the two days preceding the Show, all attendance records for the event are expected to be broken.

• RUARK SPEAKS TO FOR-EIGN TRADE ASSN.—B. W. Ruark, general manager of MEWA, was key speaker to 37 delegates from nine European countries on Nov. 6 at the Sheraton Hotel in Chicago.

Mr. Ruark, who discussed the function of trade associations, was assisted in the discussion by Martin Fromm of Martin Fromm and Associates. Mr. Fromm stressed the promotional aspects of trade association work.

• SPRAY PAINTING SCHOOL—More than 2,500 students have attended the spray painting school sponsored by the Binks Manufacturing Company, Chicago, since 1949. According to the company, the students learn how to select the correct equipment for the job and how to maintain this equipment.

Conducted every month of the year, except July and August,

the classes are limited as to number, to offer maximum individual attention.

GLASS CONVENTION—
The tenth annual convention of the National Auto and Flat Glass Dealers Association witnessed the association's first trade show. Suppliers installed 34 booths for the industry's investigation. Discussed were problems of stocking glass. Also selling and advertising, and servicing and installation problems.

• EXECUTIVE CITES FUEL BOOST—The catalyzing effect of today's 100-octane motor fuels is needed by some 1958 automobiles. This was the thought expressed to the Automotive Old Timers by Dr. Charles L. Thomas, director of Sun Oil Company's Research and Development Dept. "Some 1958 models use up to 400 horsepower," Dr. Thomas said. "This power would not be possible without a corresponding increase in the octane quality of gasolines."

He pointed out that compression ratios have increased from a 1947 average of 6.5 to today's 8.9. For the same period, horsepower has risen from 115 to 230.

Operation

JOBBER

Check Your 1958 Program

A CCORDING to the 37th edition of "Automobile Facts and Figures," published by the Automobile Manufacturers Association, 1956 set a record for the number of registered drivers in the United States. Over 77,800,000 people carry operator's licenses. In fact during 1956 alone, 3,180,000 drivers were added to the ever-increasing total who chalked up a record of 628,000,000,000,000 vehicle-miles. This averages about 8,000 miles per individual.

These impressive figures give a green-light to the tremendous sales and marketing opportunities in the Automotive Service Industry next year. For both manufacturers and jobbers.

Making sound selling, advertising, and merchandising plans for the big sales year ahead are MUSTS.

Have we a check list to use? Yes. By reviewing these items we'll know better how and what to advertise:

What to Advertise

- 1. By all means advertise your name, service slogan, phone number and addresses of main store and branches.
 - 2. New lines, since they have

news value. You can quickly "tie-in and cash-in" with the advertising and promotional campaigns of the manufacturers of these new lines.

3. Special or seasonal drives often account for spectacular and speedy increases in sales volume. Make a list of all the drives planned for the year. Even better, make up a calendar with start and stop dates for each promotion.

4. Automotive jobbers neglect advertising of machine shop services. Work with your leading suppliers whose products fit into the machine shop operation. Then build a special campaign that features the range, quality and speed of service. Build up the experience of the highly trained mechanics of shop employees.

5. Sell your salesmen. Send out sales bulletins or postcards carrying pictures of your salesmen. Tell about their background, how they can help your customers do a better buying and selling job.

6. The management of your company is one of your greatest business assets. Let the trade know the vast number of years your organization and its key

people have been faithfully serving the trade.

7. Your counter salesmen are important. They face your customers and prospects every day. Tiein your countermen and associate their names when you recommend a product or service to the trade.

8. Don't forget your nationally-known, highest quality products that have already been presold to your customers and prospects. No other business organization in your community can give quick service on parts, accessories, tools, equipment and supplies for all vehicle makes.

Delivery Service

9. If you operate pick-up and delivery service make sure this special service is known and understood. It costs a great deal of money to operate, so why not make this unique selling tool pay as big dividends as possible.

Set your selling sights high. Plan a well integrated advertising and merchandising campaign. Tie your local promotional plans into the efforts being made in your behalf by the manufacturers, whose lines you represent. Then 1958 CAN BE YOUR BANNER YEAR!

Motor Age's Who's Who



David G. Collins has been named vice president of SpeedWay Manfacturing Company of Cicero, Ill., a subsidi-

ary of Thor Power Tool Company of Chicago. He will be in charge of the Electric Motor Div.

John Towler, general manager of Sparton Automotive Division has been elected a vice president of the parent company, Sparton Corporation, Mich.



Edward F.
Bauman has
been promoted
to director of
Purchasing
Staff Activities
for FederalMogul - Bower

Bearings, Inc. He was formerly Director of Purchases for the firm since 1940.

Dan T. Bradley has been named vice president and technical advisor and Frank S. Treco, Jr., has been appointed general sales manager of Clevite Harris Products, Inc.



Jack S. Truax has been promoted to Zone Manager of the Fram Corporation of Providence, R. I. He will have head-

quarters in Minneapolis and will cover North and South Dak., Minn., Wis. and part of Mich. C. E. Johnson has been appointed sales manager of the Original Equipment Division of Alondra Sales, Inc., Los Angeles.

Frank I. Goodrich, vice president-administrative of the Eaton Manufacturing Company, was elected a director of the company.



Frank C. Maley, left, and Frank Montry have been appointed to the sales staff of Merit Mufflers. Maley will be territory manager in Western N. Y., and North Central Pa. Montry will serve in the Chicago area.



Joseph N. Stafford, left, and Jack H. Allen have been appointed new territory managers for The AP Parts Corporation. Stafford will headquarter in Nashville and Allen will headquarter in Newport, Ky.

Carl L. Kahlert has been appointed acting manager of the Replacement Division of Thompson Products. Inc.

C. E. Flora has been appointed manager of industrial sales of Davey Compressor Co., Ohio. J. E. Bickel, formerly Director of Merchandising of the Monroe Auto Equipment Company, was made vice-



president in Charge of Merchandising at the company's annual meeting.

Adrain R. Fisher has become chief executive officer of Johns-Manville Corporation when he was elected chairman of the board. He also continues as president and director of the company. Clinton B. Burnett was elected executive vice president and made a director of the firm.

Robert Twells
has been appointed Group
Executive in
charge of
Spark Plug Division of the
Electric Auto-



Lite Company. He was made a vice president of the company in 1948.

Frank Potts has been appointed assistant to Karl A. Roesch, vice president of The White Motor Company and general manager of the Autocar Division, Exton, Pa.

Frederick H. Guterman has been elected a vice president of Allen B. Du Mont Laboratories, Inc.

J. S. Mather,
Jr., has been appointed Director of Sales for the Textile-leather Division of the General Tire



and Rubber Company. He was formerly general sales manager.

signs of the times

AP Corp. Sells Power Division

The Miracle Power Products Corp., Cleveland, has purchased The Miracle Power Division of The AP Parts Corp., according to AP President, Ralph G. Rule.

Rule explained that AP will expand the products and services of its exhaust system. AP has operated the Miracle Power Division, producers of additive-type products, for the past ten years.

Jerrold Snett, vice president and general manager of the newly formed Miracle Power Products Corp., said the Cleveland firm is associated with the Eveready Pressurized Products, Inc.

Enlarge Distribution

Snett said the new company would enlarge its distribution methods with automotive wholesalers and car manufacturers. He added that military and civilian aviation fields would be strengthened.

Grizzly Holds Brake Clinic

Another in a series of Grizzly Brake clinics was held recently in Campbell, Calif., at Bev Arntzen Automotive Service. Some 50 proprietors, foremen and brake specialists from local garages, service stations and brake shops attended.

The clinics are part of a nation-wide program to acquaint operators with new products and latest maintenance methods.



NSPA 1958 Convention Program Committee: Center front: Marty Bazner, Sr., (chairman), Ammco Tools. Seated around the table left to right: Elmer Cleson, Jr., NSPA staff; Leonard Stout, NSPA staff; William Hodges, Bill Hodges Auto Parts; Frank A. Brusek, Motor and Axle Parts Service; S. J. Mack, M ar.d L Motor Supply Co.; Russ W. Case, Jr., The Chilton Co.; Howard McMurchie, NSPA staff; Ray Barnett, The Irving-Cloud Publishing Co.; Harold Johnson, Sidles Co.; Vern Olcott, Jr., Red's Motor Parts; D. D. Minshall, Gates Rubber Co.; Norman Parker, H. H. Parker and Son; Herman Teetor, Perfect Circle; J. L. Wiggins, NSPA Executive Vice President. Absent from photo: Les A. Thayer, Bel-Den Mfg.



A special "Saturday Evening Post Citation for Creating Consumer Demand" was presented to Mustang Replacement Engines and C. A. Dunmore (left), executive vice president, during the Mustang Trade Press Conference held in Garland, Texas. Post's "Ham" Cochran (right) made presentation.

MEWA Announces Essay Contest

"On-the-Job Training" will be the theme of the 1958 convention essay contest for MEWA's Young Executive Group. Contestants will discuss how on-thejob training boosts efficiency and work morale.

The Motor Equipment Wholesalers Association has limited essays from 500 to 2,000 words. Essays must be written by a registered Young Executive Group representative.

The three winners will receive government bonds and scholarships to executive development schools. The first place winner will attend MEWA's national convention, February 17-19 at Los Angeles. Closing date for contest is midnight, January 5.



Delaware Valley's Automotive Old Timers gather in The Barclay Hotel, Philadelphia, to hear Sun Oil Company executive, Dr. C. L. Thomas, describe the inseparable bond between petroleum and today's automobiles. Dr. Thomas in photo is between R. A. Harp (left), Philadelphia AOT Council president and Leslie M. Peat, executive secretary of AOT.



H. B. Barrett, President, Barrett Equipment Co. (rt.), presenting the Grand Prize, a B-500UP Drum-Dokter Lathe, to Charles Channell, service man for Willard Karl Motors, Pasadena. Presentation was made during opening of the Barrett Los Angeles office. Assisting is Gerry Stearns, Director, Barrett Brake School; R. L. Stotlemeyer, Assistant Sales Manager and I. M. Gregory, Barrett's West Coast Regional Manager.

New FATA Clubs Given Salute

Future Automotive Technicians of America clubs were given a solid indorsement at the recent Minnesota Trade and Industrial convention. J. Ray Riley, representing National Standard Parts Association, told the convention that only the nation's high schools can ease the growing shortage of automotive technicians.

Riley, in behalf of NSPA, himself a former director, presented a check to the new FATA for organizational purposes. The FATA was initially proposed as a Minnesota organization, but the group's program spring-boarded to a national level.

Riley said a survey revealed a growing awareness of school officials to youthful opportunities in the automotive industry.

Gillhouse to Head Compressor Group

Loren Gillhouse, Sales Manager of Quincy Compressor Company, has been elected president of the Air Compressor Research Council. He succeeds D. R. B. Robson, President, Keystone Compressor Company.

Accepting the position, Gill-house warned against failure to make themselves truly competitive. "We can meet this challenge," he said, "by improving our technical field service comparable with advances in compressor design and construction."

Klaus to Address Convention Groups

Charles A. Klaus, director and vice president of sales of Maremont Automotive Products, Inc., will address the 11th Annual NADA Equipment Exhibition. The exhibit will be part of the 41st Annual Convention of Na-



Joanne Boyne, hostess for Chicago's Leisure Time Exposition, helps display the Maremont Trophy awarded each year to one of the nation's top hot rodders. Assisting is Jim Lamona, events director of Automobile Timing Association of America.

tional Automobile Dealers Association. The convention will take place at the Miami Beach Auditorium, January 11-15.

Klaus, a veteran of the exhaust system parts business, will speak on "Muffler Service and Profit." He is a former president of NSPA.



T. C. Watkins was elected president of Automotive Wholesalers of Texas. Other officers above are (bottom row, left to right) Fred D. Pinkston, first vice president; T. C. Watkins; J. M. Vesmirovsky, past president; Mrs. H. G. Baker, secretary; (top row, left to right) Poncho Oatman, treasurer; G. E. Williams, assistant director; W. E. Woods, second vice president; G. C. Morris, executive director.

Freedlander Cited By Norway Award

A. L. Freedlander, chairman of the board of Dayton Rubber Company, has been named a Knight of Norway's Royal Order of St. Olaf. The award is the highest Norway can bestow upon a civilian.



A. L. FREEDLANDER

The Honorable Thor Brodtkorb, representing the King of Norway, singled out Freedlander "for his contribution to the industrial progress of Norway over the past 25 years. He helped Norway to help itself," Brodtkorb said.

Lawn Mower Award To Motor Producer

The National Lawn Mower Dealers Assn. presented their award to Briggs & Stratton Corp., Milwaukee, producers of 4-cycle engines. The award was the first of its kind given an engine manufacturer.

Presented at the National Hardware Show in New York's Coliseum, it was given for overall contribution to the Power, Lawn and Garden Equipment Industry.

MEWA Directors

The following have been elected directors of Motor and Equipment Manufacturers Association for the 1958-59-60 term. K. W. Foust, Bonney Forge and Tool Works; T. S. Rose, Sealed Power Corporation; C. O. Spillman, III, Associated Producers Inc.; and R. H. Wilbur, The Kendall Company.

Industry Meetings

Feb. 3-6, 1958 — Automotive Accessories Manufacturers of America exposition, Navy Pier, Chicago.

Feb. 8-9—Automotive Wholesalers of Oklahoma convention and booth conference, Municipal Auditorium, Oklahoma City.

Feb. 18-19 — Motor & Equipment Wholesalers Association convention, Statler Hotel, Los Angeles.

Feb. 18-19 — National Standard Parts Association convention, Ambassador Hotel, Los Angeles, Feb. 20-23 — Pacific Automotive Show,

Feb. 20-23—Pacific Automotive Show, Pan Pacific Auditorium, Los Angeles.

Apr. 23-25 — Southeast Automotive Show trade conference, Bon Air Hotel, Augusta, Ga.

Hotel, Augusta, Ga.

Apr. 27-29 — Michigan Automotive
Wholesalers Association, Pantlind
Hotel, Grand Rapids.

May 11-14 — Automotive Engine Rebuilders Association convention, Sheraton-Park Hotel, Washington, D. C.

June 15-16—Automotive Wholesalers Association of Alabama convention, Birmingham.



Thermoid Company of Trenton, N. J. announces the opening of the above westcoast warehouse at 129 Sylvester St., South San Francisco. Storage and shipping space totals 20,000 sq ft. with an additional 1800 sq ft for offices. Thermoid's automotive and industrial sales representatives will operate from this site. J. Dale Evans has been appointed manager.

Automotive Wholesalers' Sales and Inventories

Data from Bureau of the Census, Department of Commerce

Per Cent Change

	Sales			Inventories		
Region	Sept. 1957 from Sept. 1956	Sept. 1957 from Aug. 1957	9 Mos. 1957 from 9 Mos. 1956	Sept. 1957 from Sept. 1956	Sept. 1957 from Aug. 1957	
					Aug. 1001	
New England	+ 5	- 2	+ 9	+ 3	+ 4	
Middle Atlantic	- 2	- 2	+ 6	0	- 4	
East North Central	+ 4	4	+ 9	+ 2	+ 1	
West North Central	+20	0	+11	+ 8	- 1	
South Atlantic	- 4	- 2	+ 4	+ 5	0	
East South Central .	+13	- 1	+ 8	+12	+ 3	
West South Central		- 7	+ 6	+ 7	+ 3	
Mountain	+30	4	+11			
Paific	+ 4	+ 2	+ 4	- 9	- 3	
		-	-		-	
United States	+ 8	- 1	+ 6	+ 5	+ 1	

Indicators of Business Activity

These figures are based on latest thirty-day reports

	Latest	Month	Year	Percentage	Change from—
	Data	Before	Age	Month Ago	Year Ago
PRODUCTION					
Motor Vehicles (Units) Industrial F. R. B. 1947-'49 = 100 (Adj.)	417,936 142	341,407 144	485,759 146	$^{+22.4}_{-1.4}$	$-14.0 \\ -2.7$
SALES					
New Cars	460,000	495,217	424,414	- 7.1	+ 8.4
	5,901,827	6,488,365	5,237,738	- 9.0	+12.7
Durable Goods Non-durable Goods Department Stores, 1947-'49 = 100	\$14,114	\$14,297	\$13,449	- 1.3	+ 4.9
	\$14,122	\$14,341	\$13,697	- 1.5	+ 3.1
	121	128	122	- 5.5	- 0.8
GENERAL					
Consumers' Price Index, 1947-'49 = 100	121.1	120.0	117.7	+ 0.9	$^{+\ 2.9}_{-\ 0.3}_{+31.3}$
Civilian Employment	06,005,000	65,674,000	66,174,000	+ 0.5	
Unemployment	2,508,000	2,552,000	1,909,000	- 1.7	

An Open Letter to Automotive Wholesalers . . .

Advertising in the trade press is the finest possible support for you.

It is your customer, the repairman, who decides which <u>brand</u> of product to buy for almost everything you sell—not the public, not the car owner. And this brand decision is almost always made by the man your salesman calls on. Perfect Circle has called him "the Doctor of Motors." And the function of advertising is to sell him on <u>specific brands</u> of automotive parts, accessories, supplies and equipment.

When your supplier presents a dominant, consistent month-after-month campaign in the automotive trade press, it is the very best move he can make to lessen sales resistance, to increase your volume and therefore to increase your profit.

When MOTOR AGE is chosen as the foundation of his automotive trade press campaign, it is because MOTOR AGE has carefully selected, through personal interviews, exactly those of your customers who are guaranteed to do their share of at least 80%, and probably 94%, of the automotive service volume.

MOTOR AGE is the only automotive service publication which can and does make that guarantee, and therefore controls its distribution to just those shops which are your <u>important</u> customers and prospects.

Only MOTOR AGE makes a money-back <u>guarantee</u> to the advertiser that the shops receiving MOTOR AGE do 80% of the repair volume, buy 80% of the parts and buy 80% of the equipment and supplies. (The difference between the 80% guarantee and the 94% actually delivered is our "hedge" against market changes.)

One important thing that has been proved about MOTOR AGE in 8 big surveys among your customers, is that MOTOR AGE has more people actually reading it than any other automotive service book. And among those readers, MOTOR AGE has the greatest prestige.

Your suppliers' campaigns in $\underline{\text{THE}}$ $\underline{\text{NEW}}$ $\underline{\text{EXPANDED}}$ $\underline{\text{MOTOR}}$ $\underline{\text{AGE}}$ are the ultimate in advertising support to increase your profits.

RUSSELL W. CASE, JR. PUBLISHER

MOTOR AGE

newscoop

Dual Air Conditioners
Rear Suspension Changes
One Year Warranties
GM's Basic Body Shell
Low Car Woes
Hardtops Gain

In the days ahead HERE'S WHAT TO LOOK FOR!!!

Dual Air Conditioners

WHAT NEXT? Dual air conditioners for cars One auto company to bring out twin air cooler system soon One unit up front, other in trunk.

Changes In Rear Suspension

NEW APPROACH to independent rear suspension, elimination of front seat transmission explored Method involves shorter, more compact transmission Gear-box enclosed in rounded housing about size of converter in diameter.

With assembly mounted closer to engine, transmission would extend back into fire wall four inches Permits flat floor in front Propeller shaft runs into differential bolted to underbody, permitting independent rear springing.

More Psychological Than Real?

ONE-YEAR WRITTEN WARRANTIES being considered by auto companies Ford may be first to announce Value may be more psychological than real.

One company notes that 90 per cent of its warranty work done by dealers is already extended beyond 90 day period Reason: Customer pressure for better quality.

Body Shops, Attention!

CHRYSLER CORP. now using unique system to fasten exterior side mouldings Eliminates drilling holes in body, major cause of water leaks and rust.

Mouldings snap onto metal "retainers" then spot welded along body Winged-type clip inserted into inside wall of moulding, "locks" over retainer.

One Basic Body Shell

BASIC BODY SHELL in '59 being considered by GM Exception: Cadillac Reason: Saving in body tooling costs.

Use of different quarter panels, hoods, deck lids to provide individuality for each line At present GM uses three body shells.

Low Cars Bring New Woes

LOW CARS bringing woe to Michigan's traffic engineers Yellow nopassing lines on hills, lengthened to compensate for lowness of cars.

Past standard called for sight distance on grades from point 4½ feet above ground to similar sight 1000 feet away That standard now outmoded, traffic engineers say Drivers not getting maximum vision from lower seat position when going uphill.

Eyes Medium Priced Field

MERCURY'S LOW-PRICED Medalist series reintroduced This series dropped last year Hopes for more sales in medium price field Will sell for \$100-\$125 under Monterey series.

Fuel Economy Boosts Sixes

SIX-CYLINDER ENGINE expected to hold its own Reason: Renewed interest in fuel economy Sales share of sixes declined in '57 Percentage-wise decline not as great as in previous years.

Chevrolet sixes went into 38 per cent of '57 cars, compared with 40 per cent in '56; 55 per cent in '55.

Ford V-8's lost ground this year Percentage of installation dipping to 86 per cent from 89 in '56.

Closing Price Margin Gap

PRICE MARGIN between Ford and Chevy narrowed Plymouth moves to scale down prices to closer parallel Ford, Chevy.

1957 price between Plymouth's, Chevy's low-end model, about \$55 Margin for '58 reduced under \$20.

Plymouth's '58 prices average 2.9 per cent higher than '57 Chevy upped prices 5.7 per cent; Ford, 2½ per cent.

Forerunner Of New Development?

NON-FUNCTIONAL GIMMICK in roof panel over backlight on Chevy's Impala originally designed to accommodate new type ventilating system Division planned it for '58, but ran into problems These, it hopes to solve soon.

Swinging Door Problems!

NEW TREATMENT in car doors may soon show up One company thinking of hinging back doors at rear pillar Cadillac Brougham recently revived it.

Advantage: Easier entry into rear compartment However to become practical, door locking devices must be improved.

Boom In Replacement Sales

AUTOMOTIVE REPLACEMENT sales next year expected to approach \$5 billion Figure based on manufacturers' selling price.

Retail sales expected to reach \$9 billion This includes \$5 to \$5% billion in parts sales, excluding tires Also \$4 billion in customer labor sales.

Reasons: Rising number of cars, trucks Increasing need for repairs on cars produced in '55.

Brighter Outlook For Independents

SITUATION BRIGHTER for two independent automobile companies American Motors reports net profit exceeding \$1 million in Oct.
Rambler sales for year topped all records First 10 months totalled 77,318, surpassing '55.

Studebaker-Packard continues in red, but reduces losses considerably Nine-month period company lost \$12.3 million, lost \$49.6 million last year.

Third quarter loss fell sharply under same period last year From \$14.1 million to \$5.5 million.

Gains Made By Hardtops

HARDTOP MODELS in '56 accounted for nearly one-third of car sales Gains made in this body style illustrated in 1957 edition of "Auto-mobile Facts and Figures," published by Automobile Manufacturers Assn.

In 1956 hardtops took 31 per cent of market This was four percentage points more than during '55 Nearly double the share in '54, when they accounted for only 17.1 per cent of sales.

Two, four-door sedans losing ground. In 1956 they accounted for 53 per cent of market This compares with 59 per cent in '55; 73 per cent in '54.

Washington Wire



Looking For Tax Cut?

DON'T: No cut in federal taxes foreseen in '58 or anytime soon Greater defense spending to offset Russian missile successes, the reason Pressure on for increase of \$2 billion military spending in '58 Remote possibility that taxes may be increased.

Six Million Cars: Sales Goal

DEALERS MAY SELL more than six million cars in '58 Forecast made by Byron J. Nichols, Chrysler Corp. v-p and general manager of marketing.

1955's bought on installment terms ripe for trade-in, he said Finance men figure buyers will pay more to finance new cars Perhaps \$2.50 more per \$1,000 borrowed.

Spotlight Used-Car Sales

SENATE auto marketing subcommittee may spotlight '58 used-car sales. Sales, financing and insuring of cars may be studied.

Group heard testimony earlier in year on blank-contract deals, too-high collision insurance rates.

NADA's Plans On Servicing

NADA'S COMMITTEE on auto servicing responsibility changed approach in drafting new plans on servicing Chief factors: Legality of plans, needs of dealers.

Victor Hansen, U. S. Assistant Attorney General, suggested two previous proposals might be legally doubtful (Motor Age, November, 1957).

Is Business Levelling-Off?

INDICATIONS point to levelling-off period Business experts say the worst that may happen will be: Mild decline, closer cost squeeze on seller.

Federal Reserve Board frees more funds as offset to any general slide in business Action may produce another jump in credit buying.

Upgrading Of Skills

UPGRADING OF WORKER skills is first line problem for country, as U. S. Labor Dept. see it Skills must be better in order to produce enough for 193 million people by 1965.

Output of goods, services must be boosted to \$560 billion for that year It will take another 10 million fully trained workers to do job.

Are Car Prices Too High?

AUTO INDUSTRY executives to talk about car prices before Senate group Sen. Kefauver will argue that industry pricing practices cost public too much money.

Chrysler, GM, Ford, American Motors to be represented Another witness is Walter Reuther, UAW chief.

Marketing Areas With Greatest Expansion

PACIFIC COAST and Rocky Mountain states are marketing areas expanding with greatest speed New customers moving into these areas by thousands.

Eleven Western states added 4.5 million people since 1950
That's pickup of 23 per cent, compared to national average of 11 per cent Arizona, Nevada lead with increases of over 40 per cent each.

Supply Of Mechanics Growing

SERVICE STATIONS taking maintenance, repair work can expect supply of new auto mechanics to climb Govt. figures show 10,000 training to become mechanics.

In 1956 4 per cent of auto mechanics were in gasoline service stations.

Tire With Inner Tire Developed

NEWLY PATENTED is tubeless tire designed to give added protection in case of puncture It's inner tire takes over when outer surface is spiked or slashed Immediate repairs not required.





A FLUSH

and a Full House

George Bingham found that time, effort and ingenuity are the equal of underwork and a non-expanding shop


six more.

shop is small, in fact, there's room for only three cars. Outside parking accounts for

M OST small garage operators labor through periods of over-work and under-work. One week they have more business than they can handle. The following week they sit idle and do practically nothing. During busy weeks they wish they had an assistant. The next week they're glad they don't. Add this dilemma to a non-expansive location and you have a real problem. One man we've met had this problem and licked it. Here's his story:

George Bingham operates a small service garage in the residential community of Ridley Park, Pa. His shop has been in operation for many years. Homes and several businesses have risen up around him. The On immediate following pages (38 and 39) are photos of how-to-do-it radiator repair.

Like his competitors, George Bingham found himself faced with depressing periods of under-work. He began casting around for an additional automotive service. A survey of surrounding Ridley Park communities revealed car dealerships, service stations—everything but a competitive radiator repair shop. George wasted little time. He purchased a radiator repair assembly, spent his (Continued on page 72)










Radiator repair shown in ten steps

- 1 Automatic heater controls on the side of the tank hold the temperature constant. The right-hand control is the thermostatic setting.
- 2 The mechanic submerges the plugged radiator in a solution for hot cleaning. He will then clamp the lid and allow the radiator to cook.
- 3 After hot cleaning, the radiator is placed in a flushing cabinet and air pressure is injected for a thorough internal cleansing.
- 4 Still in the flushing cabinet, the radiator is submitted to high pressure water in order to remove bugs and dirt embedded in core.
- 5 Radiator has been submerged just below the water line to detect air leaks. Note the air escaping through small leaks in the core.
- 6 This close-up view reveals one of several holes to be repaired. The copper cooling fins are easily pushed back for repairs.






- 7 Here the fins are opened permitting access to the damaged area. Gas torch heat is applied while the mechanic swabs with liquid flux.
- 8 Wire solder is used to fill the hole. The radiator is then submerged and again checked with air pressure for leaks.
- After the leaks have been repaired, the copper cooling fins are straightened with a pair of long nosed pliers.
- 10 The radiator, now finished, is replaced in the flushing cabinet and sprayed with a special non-insulating black paint.












Fig. 1 depicts top and lower seats in radiator's filler neck; figs. 2, 3, 4, and 5 show variety of styles for pressure caps.

Be sure the PRESSURE CAP WORKS

OLD weather makes service specialists become more acutely aware of cooling system problems. They see so many of them. The motorist who waited till the last minute for anti-freeze. The car owner who all summer postponed renewing worn radiator hose; who held off on a new pressure cap or thermostat installation.

What was the general rule in the past as to cooling system problems? In the older models with atmospheric (non-pressure) systems, low horsepower engines, low compression, and less heat volume was the pattern. The vehicles ran pretty well if the systems were clean; in good mechanical condition.

On the other hand, with the coming of the pressurized cooling systems, the answer is not as simple. We all know that pressurized systems came into the spotlight when radiator size was cut down. When higher compression ratios and more horsepower became the rule of the modern engines. In short extra cooling capacity was needed. Pressurized cooling systems was the answer.

By pressurizing the system, the loss of coolant by evaporation, surging, and boiling was either cut down or eliminated.

Pressurization is done by using a special design filler neck. And the vitally important pressure controlling cap. The filler neck is made with a top sealing seat and a lower inside sealing seat.

The pressure cap is also equipped with a built-in pressure control valve. This valve seals off the cooling system from the overflow tube and the atmosphere. The great advantage here is obvious. The system pressurizes itself as the coolant becomes heated. The greater the heat, the greater the pressure and cooling system efficiency.

The pressure cap functions as a safety valve. It keeps the pressure within desired limits. Some pressure caps operate at four pounds, some at seven. Others go as high as 13 and 14 pounds.

Pressure caps are equipped with a vacuum relief valve which opens automatically when the engine is cooling to prevent a vacuum in the system. (The internal pressure drops below the atmospheric pressure when engine is in the process stage of giving off heat.)

Testing the Pressure Cap

A number of pressure caps have a pressure valve and spring within a cage or domeshaped part. A sealing gasket is usually carried on the bottom of the cage to seal against the lower inside sealing seat of the filler neck.

Test the tension of the pressure valve spring by inserting a piece of stiff wire or a nail through the center hole in the bottom. Press inward at the same time. This should disclose a stuck valve. The vacuum valve is also visible through the holes on the underside.

If it can be shifted easily from side to side slightly, and the light spring is holding it in place against the pressure valve, it is working properly.

However, there is a better way to test. A way that is worth the little extra trouble. A way that is safest. The best insurance against "customer come-backs."

Use a pressure tester to check the cap's condition. At the same time, the pressure tester can be used to check on the cooling system of the customer's car.

By this method, worn, leaking hoses are (Continued on page 88)

Knowing what to quick check on the pressure cap and how the cooling system should be pressure-tested are basic items to alert Servicemen



Pressure tester used to uncover leak; note water spurting from upper hose.



Studebaker's Transtar two-ton model for '58, powered by 289 cu in. V-8 engine.

STUDEBAKER TRUCKS OFFER FOUR ENGINES

New Studebaker Transtar line ranges from half-ton pickups to two-ton heavy duty trucks. Optional four-barrel carburetion will widen the power choices

WIDE range of engines, models and gross vehicle weights highlights the Studebaker line of Transtar trucks for 1958. Major highlights of Studebaker trucks for 1958 include: Powerful engine and high gross vehicle weight; five models in the twoton medium and heavy-duty series; automatic transmission for the one-ton classification; power steering for the one to twoton models; power brakes for light-duty model; premium features package for light-duty model engines and large engine for light duty units.

New Truck Line

The new Transtar line for 1958 ranges from half-ton pickups to two-ton heavy duty trucks. Four engines will be offered for Studebaker trucks in 1958. A 259-cubic inch, 170-horsepower V-8 is offered in the half and three-quarter-ton models and a 289-cubic inch, 182-horsepower V-8 will be used in the heavy-duty units and as optional equipment for the two-ton medium-duty model. This engine also is optional in the one and one-and-a-half-ton models.

Optional four-barrel carburetion will widen power choices available, increasing horse-power to 178 and 192 respectively for the 259-cubic inch and 289-cubic inch V-8 engines. Studebaker-Packard offers two six-cylinder engines available in the light-duty models, the 185 cubic inch, 92-horsepower and the 245-cubic inch, 106-horsepower power plants.

(Continued on page 74)

DODGE HEAVY TRUCKS GET AUTOMATIC SHIFT



Pickup models will carry the option of a 204-hp V-8, or a 120-hp 6 cylinder motor.

The Chrysler member has also extended Torqmatic to its medium-weight models

> chassis. Four-speed Transmission


THE convenience of automatic shifting. an integral part of today's passenger cars and light trucks, is now extended to Dodge's medium and high-tonnage 1958 trucks. Entitled Torqmatic, the shift is a mixture of six forward speeds, reverse and a hill retarder. Dodge is offering the Torqmatic on its D500, 600, 700 and S500, 600, and 700 models with a V-8 engine.

A new engine, a 207 horsepower version colorfully named the "Sugar Power Giant 315," is standard on the C600 cab-over-engine model. The double-rocker-shaft V-8 engine is available on all medium-tonnage

Another engine advancement is the fourspeed auxillary transmission for 900 models. This transmission features two underdrive ratios, direct drive, and one overdrive ratio. One underdrive ratio is for off-road servicing, while the other is designed for road gear-splitting. Dodge's extra-heavy duty, five-speed, synchro-shift transmission is continued on 900 models and will be available for the 800's.

models, except the P400 forward-control

Overall, the Dodge truck line offers ten different horsepower engines ranging from 113 to 234 horsepower. Push-button driving controls again are available on low-tonnage (Continued on page 78)



CHEVY adds 12 new trucks

HEVROLET for 1958 offers 128 models, 24 different wheel bases and five basic engines. The new trucks feature new styling; new 348-cu in. V-8 engine; a dozen new models; new series numbering system; dual headlamps; a light duty version of the 283-cu in. engine; improved engine fans and optional front axle drive on 4-wheel drive models.

New series designation consists of two numbers—31, 32, 36 and 38 for light duty models; 40, 50 and 60 for medium duty models; 70, 80, 90 and 100 for heavy duty models. Individual models have a four number designation. For example, a new model in the medium duty line with 19,500 lb GVW rating is designated as Model No. 6703H.

New Models

The new models include (1) six 2-ton low-cab-forward and chassis models with a 72-in.

(Continued on page 80)

Complete truck line now lists
128 models with 24 different wheel bases

Chevrolet's forward-control Step-Van.





Ford's tilt cab flanked by the Styleside pickup. Note new grille and dual lights.

FORD TRUCKS offers variety of models

Automobile - inspired styling, consisting of a new grille, dual headlights and two-tone color, trumpets 1958 models

FORD Motor Company, with what is described as automobile-inspired styling, will send more than 300 truck models into 1958 competition. Models range from the dapper Ranchero to light, medium, heavy, extra heavy and tandem trucks.

Ford's automobile styling is reflected in the adoption of dual headlights and a crosshatch grille. The dual lights will be standard on conventional and tilt-cab trucks. A further automobile flavor—two-tone color combinations have found their way to most models.

After the first of the year, Ford will have three new engines for models of 30,000

lb. gross vehicle weight and up. Displacements will be 410, 477 and 534-cu. in. Currently, light duty trucks will benefit from the horsepower boost given to Ford's 272-cu. in. V-8 engine, now rated at 181 hp and 440 rpm. A heavy-duty version is offered at 178 horsepower and 3800 rpm.

Engine Durability

Ford engineers claim that engine durability has been hiked by modification of crankshafts, pistons, valves and camshafts. Engine efficiency was also increased by a new carburetor, higher-capacity water pump, and (Continued on page 82)

NEW V-8 ENGINE FOR GMC TRUCKS

New grille, dual headlights and a new model will make their 1958 bow



GMC pickup model displays new front look.

THE 1958 model GMC light and medium duty trucks have been introduced. The new line of GMCs features dual headlamps, new grille, hood and fenders and new V-8 engine. One new model has been introduced which ranges from half-ton units on up to highway tractors capable of hauling 90,000 lbs gross combination weight. It is a package delivery chassis of 16,000 lbs gross vehicle a new companion for the 7,000 lb and 10,000 lb GVW package delivery models.

Torquatic Transmission

A new transmission, the Allison Torqmatic has been placed in the new GMC models 370 and up through the 600, which cover weight ranges from 32,000 to 55,000 lbs GCW. The Torqmatic, succeeding the Hydra-Matic for these models, is basically a torque converter in series with a planetary gear train operated through a hydraulic control system. The Hydra-Matic transmission is remaining on the one-half through 2-ton GMC models.

A new GMC 336 cubic inch V-8 gasoline engine heads up a group of 9 gas and Diesel engines used through the GMC line. A valve-in-head 90 degree V-type, it develops 200 gross horsepower at 4400 RPM and a gross torque of 307 poundsfeet at 2,000 to 2,400 RPM. It has a compression ratio of 7.5 to 1.



The new 336-cu in. V-8 model with 200 hp.

The 336 engine, available in all models up through the 500 series, has a unit-cast cylinder block and upper crankcase of nickel chromium alloy cast iron.

Full-length water jackets surround each cylinder for proper cooling, and the $64\frac{1}{2}$ -pound crankshaft is drop-forged from heat-treated steel. Tin-plated, cam-ground aluminum pistons combine light weight fast heat conductivity and controlled expansion without permitting excessive inertia loads on bearings.

A new four-lamp system, the company claims, gives better control of light, particularly in the low beam, greater low beam see-(Continued on page 76)



"We'll have to make it higher, too!"

Presenting a table of comparative data on the high horsepower V-8 engines of 1958 cars compiled by engineering editor Joseph Geschelin

HORSEPOWER,

ANALYSIS of V-8 engines, offered in '58 passenger cars shows a mixture of entirely new engines, as well as a few examples where displacement has remained unchanged. Generally speaking, horsepower and torque increased on most of the engines. This indicates that most passenger car producers have not yet reached the end of high performance ratings.

This year will go down as the year of induction systems. Engines are equipped with two-barrel carburetors, four-barrel carburetors, six-barrel carburetors, eight-barrel carburetors, fuel injection systems, and fuel injection with racing camshafts as in the case of the Corvette. This variety of fuel handling systems has brought about a change in engine performance characteristics for engines of the same displacement. A number of passenger car producers offer from six to seven or eight engine packages, using only three or four basic engines.

Engine Specifications

Because of such compounding of engine specifications, the present analysis has been restricted to engine options having the maximum Bhp/cu.in. ratio. Where a given make has an engine which is fitted with two- and four-barrel carburetors, the table will show only the one with a four-barrel carburetor. In the few instances where an engine is using only a two-barrel carburetor, the reasons for this choice is (One) Limitation of space. (Two) Rating engines in a descending order of Bhp/cu.in. ratios makes for a better comparison of engine potential.

1958 also ushers an era of big engines.

Cylinder bores now reach up to four-inches in diameter and displacement has exceeded 400 cu.in. on several engines. For example, Lincoln and Mercury have engines of 430 cu.in. displacement; the Edsel has one of 410 cu.in. displacement; while the Chrysler 392 cu.in. engine is very close to the 400 cu.in. figure. Moreover, top speeds for some engines—particularly those with fuel injection now are up in the vicinity of 5000 rpm.

It may be well at this point to talk about horsepower ratings. The trend to increasingly higher ratings has been criticized for some time. Why are ratings still higher? Actually, there is a good reason for this, and it is not because car producers are aiming at higher road speeds. The fact of the matter is that the engine is being called upon to supply an ever increasing number of powerconsuming devices. First, there is the increased load due to dual headlamps as well as other electric and electronic devices for operating power seats, windows, tops, etc. Correspondingly larger generators are employed and these constitute a heavier drain of engine power.

But that is only part of the story. Air conditioning installations are increasing. These require a special compressor. Starting this year, a large percentage of cars will be built with air ride. This requires installation of an air compressor. In addition, most cars have power steering and that requires a hydraulic pump. Besides this, most cars specify automatic transmissions and these have hydraulic pumps that are in the power-consuming circuit all the time. By the time all of the accessory load is accounted for, the net

TORQUE RATINGS for

output of a given engine is reduced very considerably below its advertised rating.

If engine ratings were not upped, performance from the standpoint of acceleration and safe passing ability would be impaired.

Referring to the tabulation, there are four engines that top the field in maximum horsepower rating: Lincoln and Mercury are rated at 400-bhp, with a 6-barrel carburetor (Continued on page 88)

COMPARATIVE DATA . . . 1958 OHV V-8 PASSENGER CAR ENGINES

		BHP (max)	Displacement (cu in.)	Ratio Bhp/cu in.	(ib ft)	Compression Ratio	Bore/Stroke Ratie	Ratio Torque/cu in.
1.	Chevrolet Corvette (F)	290	283	1.024	290	10.5	1.29	1.024
2.	Chrysler 300C (B)	390	392	0.994	435	- 10	1.02	1,100
3.	Chrysler 300C (G)	380	392	0.969	435	10	1.02	1.109
4.	Golden Hawk (E)	275	289	0.951	333	7.8	0.98	1.152
5.	Lincoln and Mercury (A)	400	430	0.930	480	10.5	1.16	1.116
6.	Dadge D-500 (B)	333	361	0.922	400	10	1.21	1.108
7.	Cadillac-Elderade (A)	335	365	0.917	405	10.25	1.10	1.109
8.	Plymouth Fury (D)	290	318	0.912	330	9.25	1.18	1,037
9.	Plymouth (B)	315	350	0.900	370	10	1.20	1.057
10.	Chevrolet (B)	250	283	0.883	305	9.5	1.29	1.077
11.	Imperial-New Yorker	345	392	0.880	450	10	1.02	1.147
12.	Chrysler Saratoga	310	354	0.875	405	10	1.08	1.144
13.	Lincoln and Continental	375	430	0.872	490	10.5	1.16	1.139
14.	Plymouth (G)	305	350	0.871	370	10	1.20	1.057
15.	Mercury.	330	383	0.861	425	10.5	1.30	1.109
16.	Rambier Rebel	215	250	0.860	260	8.7	1.07	1.040
17.	Ambassador	270	327	0.856	360	9.7	1.23	1.100
18.		300	352	0.852	395	10.2	1.14	1.122
19.		310	365	0.849	405	10.25	1.10	1.109
			361	0.844	400	10.25	1.21	1.108
20.	De Soto Fireflite	305					1.21	1.108
21.	Dodge D-500	305	361	0.844	400	10	1.20	1.100
22.	DeSoto Firesweep	295	350	0.842	385	10		1.100
23.	Dodge	295	350	0.842	385	10	1.20	
24.	Edsel	345	410	0.841	475	10.5	1,13	1.158
25.	Oldsmobile (A)	312	371	0.840	415	10	1.03	1.118
26.	Edsel	303	361	0.839	400	10.5	1.15	1.108
27.	Pontiac (B)	310	370	0.838	400	10.5	1.14	1.081
28.	Buick	300	364	0.824	400	10	1.21	1.099
29.	Oldsmobile	305	371	0.822	405	10	1.03	1.091
30.	Dodge Royal	265	325	0.815	355	9	0.97	1.092
31.	Pontiac (A)	300	370	0.810	400	10.5	1.14	1.081
32.	Chevrolet (A)	280	348	0.804	355	9.5	1.26	1.020
33.	Dodge D-500 (G)	320	361	0.803	400	10	1.21	1,108
34.	Ford.	285	332	0.798	360	9.5	1.21	1.083
35.	Plymouth	250	318	0.785	340	9	1.18	1.069
36.	President	225	209	0.779	305	8.3	0.98	1.055
37.		285	370	0.770	395	10	1.14	1.067
38.	Studebaker Commander	195	259	0.753	260	8.3	1.10	1.023
30.	Studeoaker Communicities	100	239	0.733	200	0.0	1.10	1.020

NOTES:

- (A) Three, two-barrel (six-barrel) carbureter package.
 (B) Fuel Injection system.
 (E) McCulloch Supercharger installation.
 (F) Fuel injection with special camshaft package.
 (G) Two, four-barrel carbureter package.





Ray Scott

Philadelphia, a patriarch of formality, threw open its Convention Hall last month and graciously embraced the glittering world premiere of the 1958 Automobile Show. New York's world-famous hostess, Elsa Maxwell, and MC Ray Scott, president of the Phila. Automobile Trade Assn., welcomed the multitude of formal-attired visitors. A begoggled Elsa arrived in a 1907 Maxwell and was interviewed by show committee member John B. White. Even ancient Ben Franklin turned out to glimpse the smart American and foreign models.

PHILLY SHOW Welcomes 125,000

New American and foreign automobiles displayed before formal audience in sparkling first-night world premiere Julie Driscoll

Ray Scott

Elsa





Elsa and John B. White -





Ben Franklin



Sitting Pretty

service Man's

'Old' but not Forgotten

Several "Idea Book" awards go out this month. The first to Stan Clark in East Bradenton, Fla. Writes Stan: "We use every method we know to attract new customers, but have found it of utmost importance to keep our 'regulars' coming back." He adds that it is human nature to expend courtesy and service to impress the brand-new customer and a temptation to take the "regulars" for granted.

Stan's service center has adopted the policy that "the longer a customer has been with us, the more important he is." An old customer is a walking advertisement. He carries the word of good service and reasonable prices to friends and relatives. Don't overlook the "regular."



Above is window display featured recently by V. E. Wisniewski at his parts supply store in Milwaukee. Wisniewski's display featured Ford Model T parts. His store specializes in supplying older model parts

Service Known thru Movies

The second award this month was hauled in by Dave Hardesty, service manager for Ralph Pritts and Sons in Oakland, Md. Dave notes that the Ralph Pritts Dodge-Plymouth agency makes use of the movie theater screen practically all year round.

Quick, interesting service and sales pitches are thrown on the town's main movie house screen in Oakland. In the summer, the messages are also shown at intermissions at the local drive-in. Oakland is in the heart of the Deep Creek Lake area of western Maryland.

Two Patterns in Auto Sales

A "massive upgrading" of the automobile market and a year-round auto business free for the most part from seasonal ups and downs were cited as two patterns in the industry recently. In a talk before the American Finance Conference, Byron J. Nichols, general manager of automotive group marketing for Chrysler, said: "The trend toward 'more automobile' is the dominant trend in the market today. The roomy, comfortable all-purpose American car . . . will retain its present place of overwhelming popularity."

Secondly, Nichols saw a trend towards the leveling off of peaks and valleys in the automobile market. "In the pre-war years the third quarter sagged definitely below the second quarter. But in the post-war years the third quarter has strengthened and tended to approximate the levels of the second quarter."

Nichols sees three events helping to set up this picture. 1) The development of the allseason closed car. 2) The switch of new car introductions from January to the Fall. 3) Increased emphasis on third quarter selling.

























MOTOR AGE Indexfor1957

SPECIAL EDITORIAL FEATURES	
Month Pe	age
You Were There-National Auto Show. Jan.	37
"Consumerism" Jan.	57
"Consumerism"	60
National Highways What About	00
Service Areas?Feb.	44
Service Areas: Feb.	48
New Wreck Estimator Feb.	
The Good New Days Mar.	40
Indianapolis Preview	40
AccountingJuly	37
Accounting	39
Round-Up)Aug.	40
Wanted: 40,000 New Mechanics Sept.	42
President's Conference for Small	
BusinessOct.	55
A Flush and a Full House Dec.	37
Philly Show Welcomes 125,000 Dec.	50
Motor Age Index for 1957 Dec.	53
NEW CARS AND TRUCKS	
Month P	age
Mechanical Highlights of '57 CarsJan.	44
Survey of Optional EquipmentJan. Station Wagon Joins Packard Clipper	64
LineFeb.	50
Passenger Car Body DataApr.	58
New Scotsman BowsJuly The Edsel and its Mechanical	48
HighlightsSept.	37
Fiats New Rear-Engine Car Sept.	50
Ford Offers Air Suspension	44
Chevy's New Styling ThemeNov.	45
Longer Lower Lincoln	46
Buick Adds Luxury Model	47
Pontiac Restyles Series	48
Mercury Two New EnginesNov.	49
New V-8 Powers Plymouth Nov.	50
'Luxury' Ride for Studebaker Nov.	51
DeSoto Expands Line	52
Compact Theme for Rambler Nov.	53
Chrysler Restyles WindsorNov.	54
Cadillac's Sculptured Styling Nov.	55
Dodge Unveils Ram-Fire 8 Nov.	56
	57
Imperial Increases Length Nov.	
Ambassador Joins Rambler	58
Olds Features Air Suspension Nov.	59
Packard Hawk Family Sports Car Nov.	60
Packard Hawk Family Sports Car Nov. Continental's Mark III Nov.	61
Dodge Heavy Trucks get Automatic	42
Shifts Dec.	43
Chevy Adds 12 New Trucks Dec.	44
Ford Trucks Offer Variety of Models Dec.	45
Chevy Adds 12 New Trucks Dec. Ford Trucks Offer Variety of Models Dec. New V-8 Engine for GMC Trucks Dec.	46

EW DEVELOPMENTS	
Month P	age
Motor Age Shop Clinic Quiz Jan.	52
I'll Buy That—New Products Section Jan. National Highways What About	65
Service Areas? Feb.	44
What Happened at Daytona? Mar.	57
(Continued on page	(4)

MOTOR AGE INDEX

Continued from page 53		QUICK SERVICE	
1957 Indianapolis ReportJune	37	Month P	age
What About Parts & Service for Foreign	46	How to Lift the '57 Cars	48
Cars?June Futurize with 4-D StylingJune	60	You Can Trim Overhead Thru Power	
On the Brink of SuccessJuly	42	Mower ServiceApr.	46
Highlights of Marvel-Schebler's Fuel	12	How to Service Cooling Systems May	37
InjectionSept.	44	Steam Cleaning Pays Off	48
Mechanical Genius Invents New Speed	**	Servicing Power Mower Engines June	40
Control Sept.	46	Quick Checks to Pinpoint Generator	40
Power Lubrication by Push Button Sept.	55	TroublesJune Draining and Refilling AutomaticsJuly	42
Modern Equipment Makes Body Repairs		Locating Noisy LiftersAug.	
EasyOct.	38	Field Installation for "Minit Heat" Aug.	
Technical Spotlights of '58 Cars Nov. Horsepower, Torque Ratings for '58 Dec.	37 48	Lubricating Universal JointsSept.	
MANAGEMENT FEATURES		ENGINE KNOW-HOW	
Month P	ann	Month P	
Part I—Business Facts of LifeJan.		Pop Muffles His Anger Feb.	43
Is Money Tight for Auto Sales? Jan.	56	New Technical Developments Feb.	
Know Your True Cost of Doing		How Engines Waste Oil Apr. Pop O'Neill—Oil on Troubled Waters Apr.	
BusinessJan.	58	What You Should Know About Fuel	40
Part II—Business Facts of Life Feb.	54	Injection SystemsApr.	50
Credit: Key to Volume and Profits Mar. Part III—Business Facts of Life Mar.	46	Motor Age Shop Clinic QuizApr.	
Part IV—Business Facts of Life Apr.	54 54	General Engine Data Oil Filter Type,	
Part V—Business Facts of Life May	54	PistonsApr.	60
Part VI—Business Facts of Life June	54	Piston Rings, Piston Pins, Connecting Rods	62
A New Approach to Automotive		Crankshafts, CamshaftsApr.	66
Accounting July Selling Shop Safety July	37	Valve Timing, Lubrication and Exhaust	00
Selling Shop SafetyJuly	40	SystemsApr.	68
Management Clinic: What Is a Business		Valves, Intake and ExhaustApr.	70
Memory?Aug.	54	Engine Trouble Shooting with	
Don't Slight the Service Department Aug. Revise Our Training Methods Sept.	55	Electronics	46
Management Clinic: Finding 'Lost'	43	Servicing Power Mower Engines June	40
CustomersOct.	54	Technical Spotlights of '58 Cars Nov.	37 48
	04	Horsepower, Torque Ratings for '58 Dec.	40
MERCHANDISING AND SALES		ELECTRICAL AND TUNE-UP	
Month I	Page	Month P	age
Is Money Tight for Auto Sales?Jan.		Mechanical Highlights of '57 CarsJan.	
Wrecker Radio Links Highway and	90	Batteries Know When to Replace or	44
Home Mar	43	RechargeApr.	48
Safety Checks Sell Service Ann	44	Drive Belts, Electrical Supply Systems . Apr.	74
Steam Cleaning Pays Off	48	Starting and Ignition SystemsApr.	76
I rimming Overhead in the Body Shop May	50	Ignition, Timing, Spark Plugs, Clutches. Apr.	77
Celebrates Golden AnniversaryJuly	49	Tune-Up Data for 1952-57 Cars Apr.	82
Give Your Car a BrakeJuly	y 61	Lamp Bulbs, Fuses, Circuit Breakers Apr.	86
Profit from Summer Tune-upsAug.		Engine Trouble Shooting with	46
Why Shake, Rattle 'N Roll? Aug. Management Clinic: Can They See Their	61	Electronics	40
Way Clear?Sept.	54	TroublesJune	42
Body Shop Ups Service Volume Sept.	56	Motor Age Shop Clinic QuizJune	50
Keeping Auto Bodies HealthyOct.	37	Locating Noisy Lifters Aug.	44
Promote Winterizing Services Oct.	50	Profit from Summer Tune-ups Aug.	. 46
Don't Forget Your Anti-FreezeOct.	51	Technical Spotlights of '58 Cars Nov.	. 37
Own a Hard-Starting Car? Dec.	65	Own a Hard-Starting Car? Dec.	65

for 1957

Front Suspension and SteeringApr.	93
Wheel Alignment, Rear Suspension Apr.	94
Solving Front-End ProblemsAug.	37
Motor Age Shop Clinic Quiz Aug.	52
Why Shake, Rattle 'N Roll? Aug.	61
Examining Cadillac's Air Suspension Oct.	44
Technical Spotlights of '58 Cars Nov.	37

BODY SERVICE AND PAINTING

ODI SERVICE AND PAINTING	
Month	Page
How to Service Your Spray Gun Jan	. 72
New Wreck Estimator Feb	. 48
Building up Brightwork Business Mar	. 42
Wrecker Radio Links Highway and	146
HomeMar	. 43
Wreckers to the Rescue Mar	
Springtime Service on Convertible Tops	
and TrimMar	. 50
How to Give Interior Panels That New	
Car LookApr	. 42
Trimming Overhead in the Body Shop May	50
Replacing Door Glass on GM Cars June	48
Futurize with 4-D StylingJune	60
Quality Never Hurts Volume July	50
Tips on Hydraulic Power Systems Aug	50
Body Shop Ups Service Volume Sept	. 56
Modern Equipment Makes Body Repairs	. 50
EasyOct	. 38
Repairs With Epoxy PlasticsOct	. 41
Reconditioning Car Interiors Oct	. 42
Tips for Masking and Painting Oct	48
Motor Age Shop Clinic Quiz Oct	52
Do's and Dont's for Cleaning Stainless. Oct	. 56
Trouble Shooting Electric Window Lifts. Dec	. 62

TRANSMISSION & AXLE MAINTENANCE

Month Pe	age
Vital Facts About Turboglide	
TransmissionFeb.	37
Motor Age Shop Clinic QuizFeb.	52
Transmissions-Conventional and	
Conventional with OverdriveApr.	88
Automatic TransmissionsApr.	89
Propeller Shaft and Rear AxleApr.	92
New Synchro-Mesh Truck Transmission, May	42
Pop Reads the PapersJune	52
Servicing GMs Non-Slip Differential July	44
Draining and Refilling Automatics July	46
Motor Age Shop Clinic QuizJuly	52
Power Impact Tool for Transmission	04
Work Aug	48
Lubricating Universal Joints Sept.	40
Motor Age Shop Clinic Quiz Sept.	52
Technical Spotlights of 58 Cars Nov.	37
	0.1

STEERING, SUSPENSION, & WHEEL ALIGNMENT

	Month P	age
Mechanical Highlights of 57 Cars	Jan.	44
New Technical Developments Aligning Torsion-Air Suspension	Feb.	47
Systems	Mar.	37
Motor Age Shop Clinic Quiz	Mar.	52

BRAKES & SERVICE

MAKES & SERVICE	
Month Pe	ige
Mechanical Highlights of 57 Cars Jan.	44
Troubleshooting: Brakes Pull to Left? Feb.	67
Safety Checks Sell ServiceApr.	44
Tires and BrakesApr.	90
Unsafe Brake Fluid (Newscoop) May	33
Troubleshooting: Mercury Brakes Grab. May	59
What About Parts & Service for	
Foreign Cars?June	46
More About Brake Fluids (Newscoop) June	33
Idea Book: Selling Brake ServiceJuly	53
Give Your Car a BrakeJuly	61
The Edsel and its Mechanical	
HighlightsSept.	37
Technical Spotlights of 58 Cars Nov.	37
Troubleshooting: 56 Lincolns Brakes Nov.	65

CARBURETORS AND FUEL SYSTEMS


THE PARTY OF THE		600
	Month Pag	e
Mechanical Highlig	hts of 57 Cars Jan. 4	4
	relopmentsFeb. 4	7
What You Should I	Know About Fuel	
Injection Systems		e
The Edsel and its M		
Highlights	Sept. 3	17
Highlights of Marv		
		14
Mechanical Genius		
Control		16
Technical Spotlights	of '58 CarsNov. 3	7

RADIATORS & COOLING SYSTEMS

ķ.	ADIATORS & COOLING STOLEME	
	Month Po	age
	Mechanical Highlights of 57 Cars Jan.	44
	Fuel and Cooling SystemsApr.	72
	A Straight Flush for your Radiator May	29
	How to Service Cooling Systems May	37
	Setting Up a Radiator Service	
	Department	39
	Motor Age Shop Clinic Quiz	52
	Technical Spotlights of 58 Cars Nov.	37
	A Flush and a Full HouseDec.	37
	Be Sure the Pressure Cap Works Dec.	40

AIR CONDITIONING & SERVICE

IN COMBINIONING & SERVE	
Mo	nth Page
Cool Profits From Installing Air Conditioners	Feb. 40
Dept.	Feb. 42
More About Air Conditioning Profits	May 44
Air Conditioning is a "Hot" Item	June 44
Servicing Car Air Conditioners	Aug. 42



BODY SHOP TIPS

are worth

\$7.50

If you've developed an idea that has helped you to do body and fender work or painting better or faster, it may be worth money. Jot down the idea and, if necessary, make a rough sketch. Sometimes a snapshot will help. Just make the description of your BODY SHOP TIP clear, and if it is used, you'll receive a check for \$7.50.

Rubber Scrapper Makes Tool For Stirring Paints


When a kitchen rubber scrapper is discarded, store it in the work shop or garage with paint supplies. It makes a fine tool for stirring paints and other liquids used in the work shop. Much better than using brushes for transferring paint from one container to another. E. A. Stowell, 515 E. Oak St., Boscobel, Wis.

Tip on Removing Vent Window Glass

Sometime ago I saw in your Body Shop Tip section a tip on replacing vent windows. It advised heating of vent frame for easy glass removal. I'd like to add something to that tip. Put three or four strips of masking tape on each side of glass near open edge. Then snap a pair of vise grip pliers on. This gives you a good grip on the glass and will not crush or break glass. Bud Teske, Spencer Motors, 111 North St., Waukesha, Wis.

How To Make A Handy Body Jack

When space doesn't permit use of small body jack or spreader attachment, an efficient jack screw can be quickly made from various items found




around the shop. They are a lower pivot pin and bushing from an "A" frame front suspension and an outer front wheel bearing assembly. Tack weld cone of bearing on end of bushing opposite shouldered end. Assemble bearing and jack screw is complete. Turning bushing on threaded pin gives an adjustment of approximately 2½ inches. Dean Tarkington, Mancuso Motors Inc., Body Department, Batavia, N. Y.

Painting Wheels Without Removing The Tires

Take a piece of tin 26 inches square. Put a 17 inch wheel on the tin and mark the inside circle. Cut it out and then make the outside round, leaving the piece 5 inches across. Then cut the piece in two. Next you wrap it around a 15 inch wheel and weld it together. Put a flange on the inside of it and about 1/2 inch, pointing it toward the tire so it will go inside the bead on the wheel. Put strap iron on two sides in the form of a hook and put two spring steel bands (such as a clock spring) on the other side. This will help you snap it on the wheel so you can paint. This is for a 15 inch wheel. The same can be done to make one for a 14 inch wheel by using a 16 inch wheel to start with, instead of a 17 inch wheel. Ralph J. Hill, Foreman, Mace Motors, Inc., Canton, N. Y.





How To Remove Engine Oil Pan

Engine oil pan removal and installation is somewhat difficult on early production 1957 Mercurys equipped with a front engine steady rest support.

The following procedure has been established to remove and install the oil pan on these vehicles.

- 1. Turn crankshaft to position the No. 1 piston 12 degrees A.T.D.C.
- 2. Raise vehicle on hoist. Drain engine oil.
- Remove radiator splash shield.
- 4. Remove stabilizer bar mounting bolts.
- 5. Vehicles equipped with automatic transmission.
 - Remove oil pan cap screw securing transmission cooler line clip to block.
 - Loosen transmission oil cooler outlet pipe at lower left-hand side of radiator and right-hand side of transmission case.
- 6. Remove engine steady rest mounting bolt that secures steady rest to bracket on frame front crossmember.
- 7. Remove nuts and retainers from front engine supports.
- Remove two bolts securing rear engine support to frame crossmember.
 - 9. Remove cap screws secur-

ing oil pan to cylinder block.

10. Raise front of engine approximately 4½ inches.

Caution: Do not raise engine more than required amount to remove oil pan.

- 11. Drop front of oil pan down, position stabilizer bar between oil pan and cylinder block.
- 12. Carefully remove oil pan assembly.

To install oil pan assembly, reverse removal procedure.

Removing Glycol Contamination From Oil System

If Glycol (permanent antifreeze) contamination is present in an engine oiling system it should not be removed until the cause of the leakage is found and corrected. The following steps, if closely adhered to, will effectively remove all Glycol contamination.

- (1) Drain out all oil and remove the oil filter; fill the crankcase with a mixture of about 3 qts of SAE 10/W oil and 2 qts of Butyl Cellosolve (obtainable from chemical suppliers); idle the engine for 30 min. noting the oil pressure; immediately drain the solution from the crankcase.
- (2) Add a flushing solution of about 3 qts of SAE 10/W oil and 2 qts of kerosene; circulate the mixture at idling speed for 5 minutes; completely drain the system.

(3) Install a new oil filter element and add fresh oil of the grade and classification required.

Fuel Injection Starting Procedures

Due to the revised fuel and air control arrangement used on Chevrolet's Fuel Injection as compared to carburetor air-fuel control, the procedure for restarting a warmed-up engine is different than was required for carburetor equipped engines.

To restart a Fuel Injection equipped car while the engine is still warm, depress the accelerator to the floor and hold in this position while cranking with the starter until the engine starts. By this means, a minimum amount of fuel is added by shutting off the starting bypass fuel line while the maximum amount of air is admitted by fully opening the throttle valve in the air meter.

Cold starting procedures for Fuel Injection equipped engines are identical to those of automatic choke carburetor equipped engines. Depress the accelerator pedal to the floor to index the fast idle cam, then fully release. Crank engine until it starts. Indexing the fast idle mechanism provides the higher engine idle speed necessary during warmup.



TROUBLE SHOOTING



Having Trouble With Sluggish Brake Pedal

One of our customers is having trouble with his brake pedal being sluggish in returning on cold days. This car is a 1953 Buick equipped with power brakes. I have checked the adjustments etc. and everything seems to be in order.

Dans Auto Service Roslyn, Pa.

Toccurs to me that the trouble probably is in the power cylinder, it may need lubricating. I would suggest taking the unit

apart to carefully check the power cylinder bore and piston. The bore should be smooth and free from burrs. Then seals should be lubricated with hydraulic brake fluid and reassembled.

Hard to Start '51 Olds When It Is Hot

I have a 1951 Oldsmobile and when it is hot it doesn't start. I have done a valve job, put in new lifters and rebuilt the carburetor which is a four-barrel one off a '52 Olds. I have put a

new starter on and I have gone over the ignition system. When it is cold it starts fine, but when it gets hot the starter draws a lot of current out of the battery while trying to turn the motor over and then there isn't enough spark. I have used a 12-volt battery which kicks it over and starts it fast. If the car is pushed, it starts right up. I thought it might be a warped flywheel, I have been planning to tear the motor down because it needs rings. I think they may be cracked. When the motor is racing, oil is blown out the breather. The car has an automatic transmission.

> David J. Garland Pat's Service Station Fairport, New York

I HAVE seen quite a few Oldsmobiles giving the same trouble and it always goes back to the starter. I would suggest checking the ignition timing to make sure it is not advanced too far, also make sure all the electrical connections are clean and tight. Sometimes the problem can be licked by reworking the starter brushes. Remove the starter and file each brush to a point. Try this and see how it works. As for the oil leak, I am

FOR ADDITIONAL SERVICE INFORMATION REFER TO CHILTON'S



quite sure the rings are worn, causing the engine to have a lot of blow-by.

1956 Ford Pulls To Left When Brakes Are Applied

I am having trouble with a 1956 Ford Victoria. Every time the brakes are applied the car pulls to the left. I have had the front end completely overhauled and aligned. I've also replaced the lining three times on both front wheels; had the lining radius ground to the drums; replaced both front wheel cylinders; repacked and adjusted the front wheel bearings; bleed and rebleed the brake system. I have power brakes on the car so I disconnected the power unit. The same condition exists. I've had mechanical experts look at the car and they have all said that one of the above mentioned items is the cause. I have double checked all the above items with no results. This has been going on for a six month period.

Eugene Mateus c/o Tom's Amoco Service Clinton, New Jersey

I HEARD of similar experience on these brakes and they were corrected by either replacing both front hoses or doing what you have done already. You might try filing the brake shoes where they contact the top anchor. Best results are obtained by using a quarter to check the shoes contour at the top anchor. File the curve until the quarter just lays in it. I also ran into a case where the brake line fitting was restricted, it was not drilled properly, I would suggest checking all the brake lines for restrictions.

Wants Advice On Balky Engine

We have a 1955 Chevrolet V8 that has a peculiar miss and spits once in a while. I have tuned it up and have gone over the carburetor. Can you give me any information on this problem?

Car Conditioning Company Phila., Pa.

If the compression is good and it idles smoothly, the condition might be due to cross firing. This sometimes happens when the high tension current is flowing through the ignition cable on its way from the distributor to the spark plug. It may induce voltage in another plug wire im-

mediately next to it, especially when the two wires run parallel to each other for some distance. This voltage may cause a spark plug to fire out of sequence resulting in a miss or spit back. Cross firing is most likely to occur between the two rear cylinders in the left bank, which immediately follows each other in order of fire. The remedy for this condition is to reroute the spark plug wires so that No. 5 and No. 7 wire are not next to each other. Run the wires through the holders with 5 on one side and 7 on the other. Also make sure the plug gaps are set to specifications.




MOTOR AGE FLAT RATE AND SERVICE MANUAL



Adjustment Tool

A new E-Z Reach tool, over 18 inches long, has been offered for use on all external adjust-



ment distributors. As claimed by the manufacturer, the new tool can be used to adjust distributors with dual or triple carburation and air conditioning. It is said to be engineered to eliminate troublesome wrap - up and back - lash. Write: United Motors System, Delco - Remy (M.A.), Detroit 2, Michigan.

Cushion Toppers

A new seat cushion topper that can be installed and removed in minutes is available for 1957 Chrysler and Imperial cars, including Plymouth, Dodge and DeSoto. It is also reported available for older cars. According to the manufacturer, the seat jackets are full-fashioned for both front and rear seats and are free from annoying clothing drag. A latex foam rubber padding reputedly insures a perfect fit. It is said the toppers can be

sponged clean while remaining on the seat and require no special tools for installation or removal. The jackets are reported available in gray, black, blue, green or maroon. Write: MoPar Division, Chrysler Motors Corp. (M.A.), P. O. Box 1718, Detroit 31.

Exhaust System Sealer

A new compound that permanently seals exhaust system connections against gas leakage and noise has been developed. The company claims the compound



was developed to stop acoustical leakage of high velocity exhaust gases. It is said the self-drying compound will seal marred connections between mufflers and pipes. It will also allegedly prevent rusting of connections. Write: Walker Mfg. Co. (M.A.), Racine, Wis.

Welding Booths

Compact welding booths, de-

signed to overcome the hazards of both toxic gases and arc flashes, have been announced by the producer. It is claimed the booths feature high velocity suction, and durable steel side extensions. Reportedly, booth sizes range in height, 30-in. to 42-in., width, 30-in, to 60-in, and a depth of 28-in. to 36-in. Appropriate blowers, it is said, are available with air-movement power of 400 to 1650-cu ft per min. Write: Engwald Corp. (M.A.), 125 Sheridan Blvd., Inwood, L. I.

New Short Ram

A new short ram has been designed for inaccessible areas. It is said the Ram's closed height is 2\%-in. It will reputedly move a full inch. According to the manufacturer, the Ram will fit 2, 3, 4 and 7\%-ton jacks with quick detach couplers. Coupling is allegedly offset for positioning




and to prevent hose damage. It is claimed the Ram worked well on swept-back fins; also '58 Buick front ends, and straight

box frames. Write: H. K. Porter, Inc., Automotive Division (M.A.), Somerville, Mass.

Route, Mileage Marker

A transparent route marker




and attached mileage computer is offered for map computation. It is said the computer converts inches to miles with the map legend. The computer's gauge can allegedly be used for Canadian or European maps. The reverse side reportedly features a compass. Refilling the route marker, it is claimed, is similar to refilling a lighter. Write: DRI-FLO Mfg. Co. (M.A.), 410 E. Fifth St., Royal Oak, Mich.

Polishing Cloth

An all-purpose, heavy duty polishing cloth available in transparent plastic has been announced by the manufacturer. The cloth is available in 16 lb bags and is packaged in 3-lb six - pack, self - merchandising cartons. According to the producer, the cloth is extra-soft and absorbent for polishing cars and glass. Made of lint-free, white material, the cloth is tubular - formed in continuous double-running yardage and, it is claimed, can be cut to desired lengths or washed for reuse. Write: Atlas Textile Co. (M.A.), 1615 Woodland Ave., Cleveland 15. Ohio.

New Frame Lift

A new frame lift has been developed that raises from both lengthwise and crosswise positions. It is claimed it will support most all American and foreign cars. The lift, named H-Master Turn-About, allegedly has a non-rotating device and safety latch that automatically locks it in position. It is said to be equipped with 70-in. rails and designed for a wheelbase of 98.5in. or longer. This includes bowed frame models without adapters. The company claims smaller cars can be rotated 90deg. Eight models are reportedly available with full-hydraulic air, semi - hydraulic air, or full-hy-



draulic electric operation. Write: The Joyce-Cridland Co. (M.A.), 2027 E. 1st St., Dayton 3, Ohio.

Replacement Lenses

A new line of automobile replacement plastic lenses for dealers and service station operators has been announced. It is claimed the lenses are available in red and clear for passenger cars and trucks, and will coincide with original manufacturer specifications. Red lenses for stop and tail lights are reportedly stocked for 1957 Plymouth, Dodge, Chevrolet, Ford, Buick and Pontiac models. Clear lenses for parking, back-up and directional lights are also available.

Write: ALCO Division, Auto Lamp Manufacturing Co. (M.A.), 2909 Indiana Ave., Chicago 16.

Power Timing Light

A new AC power-timing light has been introduced, capable of checking 6, 12, 24 and 48 volts and magneto. It is said the light offers a new cooling circuit that will not burn out after hours of operation. According to the manufacturer, a narrow beam that pinpoints the timing mark is supplied by a long-burning lamp. The light reportedly requires two connections and a 110 volt power source. Write: Herbrand Tools (M.A.), Fremont, Ohio.


Test Bench Unit

A new generator-regulator test bench has been announced. It is said the unit will test 6 and 12-volt car and light truck generators at speeds up to 600 watts. Reportedly, generators without matching regulators can be tested, as well as double-contact regulators. It is claimed the unit offers forced air cooling, illuminated meters, a generator vise, and a simplified test-lead



hookup. Write: Allen Electric and Equipment Co. (M.A.), Kalamazoo, Mich.


UP TO DATE TROUBLE SHOOTING



Buick window lift. Letters A, B and C indicate where lift arm is pinned while removing motor. [Fig. 1]

Below is a view of Lincoln's type B lift with rubber coupling. [Fig. 2]

10 remove door window regulator in General Motors cars observe this procedure: Lower the window and disconnect the battery, then remove the garnish moulding and inside door handle. Pry the trim panel away from the door, disconnect the wires or terminal block from the control switch and remove the trim panel. Remove the access hole covers from the inner door panel and take out the lower sash channel cam screws, then raise the glass and support it in the upper position. Disconnect the wiring harness from the regulator motor. (On front doors remove the ventilator division channel lower adjusting stud and nut.) Remove the inner panel cam attaching screws,



ELECTRIC WINDOW LIFTS

The causes of electric window failure can be as complicated as a mystery story. But you don't have to be a Sherlock Holmes to find the solutions. Let these MOTOR AGE hints guide you. . . . By Leo A. Mealey, Jr.

TROUBLE SHOOTING

Trouble:

Windows will not operate from master switch but can be operated by individual control switches.

Possible Cause:

1. Defective switch in master switch.

Trouble:

Window will not operate from either master or individual control switch.

Possible Cause:

 Burned out motor. 2. Defective circuit breakers. 3. Broken control wires. 4. Break in wire from starter solenoid to circuit breaker.

Trouble:

Window operates in one direction only from either master or individual control switch.

Possible Cause:

1. Defective switch. 2. Burned out motor.

3. Broken control wire.

Trouble:

Circuit breaker "clicks" but window does not operate.

Possible Cause:

Control wire grounded.
 Defective switch.
 Electrical short circuit.
 Window misaligned.

Trouble:

Window operates in wrong direction from either master or individual control switch.

Possible Cause:

I. Lead wires connected wrong on switch.

2. Motor wires reversed.

Trouble:

Window rises slowly and lowers rapidly.

Possible Cause:

Broken counter-balance spring on regulator.

detach the cam from the regulator arm and remove the cam from the door. Remove the window regulator to door attaching screws and carefully work the regulator assembly out through the rear access hole.

Replace Regulator Motor

Caution: The regulator lift arm, which is under tension from the count(Continued on page 84)




Fig. 3: An exploded view of Lincoln's Type A lift.

1958 Tune-up - Alignment Specifications

	ENGIN	E				TUNE-	JP DATA	4					FRONT END	ALIGNMENT	
					VA	LVES			IGN	ITION					
MAKE AND MODEL	No. of Cylinders Bore and	ke H.P.	Spark Plug Make and Size (mm)		Seat Angle		iting pet ance	Gap (In.)	(Deg.)	Gap (In.)	Tim- ing	(*60	Caster (Deg.)	Camber (Deg.)	Too-in
	Stroke (In.)	Maximum Brake		Inlet (Deg.)	Exhaust (Deg.)	Inlet (In.)	Exhaust (In.)	Bresker Point	Cam Angle (D	Spark Plug G	Spark Occurs . T. C.	Streeting Axis Inclination (Deg.	(Deg.)	(Deg.)	(1116.)
AMERICAN MOTORS CORP.															
Metropolitan	4-23/sx33/2	52	Ch-14	48	45	.015HC	.015HC	.015	30	.024	118	814	2P to 3P	34P to 134P	0 to /s
Rambler	8-314x414 8-314x314 8-4x314	127 215 270	CA-14 CA-14 CA-14	45 30 30	45 45 45	.012H .012H Hyd	.016H .014H Hyd	.016 .016 .016	32 30 30	.035 .035 .038	58 58 59	6°11' 6°11' 6°11'	0 to 14P 0 to 14P 0 to 14P	I/N to I/P I/N to I/P I/N to I/P	点 to 点 点 to 点 点 to 点
CHRYSLER CORP.															
Chrysler 8-LC1-L 8-LC2-M 8-LC3-H 8-LC3-S	8-3+1x35+ 8-3+1x35+ 8-4x3+ 8-4x3+	290 310 345 380	AL-14 AL-14 AL-14 AL-14	45 45 45 45	45 45 45 45	Hyd Hyd Hyd .015H	Hyd Hyd Hyd .024H	.017 .017 .017 .017	30 30 38 38	.035 .035 .035 .035	8B 6B 6B	63-5 63-5 63-5 63-5	0 to 134N 34N to 34P 34N to 34P 34N to 34P	0 to 14P2 0 to 14P2 0 to 14P2 0 to 14P2	10 to 50 to 50 to 50 to 50 to 50
De Sete 8-LS1-L 8-LS2-M 8-LS3-H 8-LS3-S	8-41-x33-x 8-41-x33-x 8-41-x33-x 8-41-x33-x	280 295 305 345	AL-14 AL-14 AL-14 AL-14	45 45 45 45	45 45 45 45	Hyd Hyd Hyd Hyd	Hyd Hyd Hyd Hyd	.017 .017 .017 .017	30 30 30 38	.025 .035 .035 .035	88 68 68 88	61/2 61/2 61/2 63/2	0 to 114N 0 to 114N 0 to 14N 0 to 14N	0 to 14P2 0 to 14P2 0 to 14P2 0 to 14P2	A to A to A to A
Dodge 6-LD1-L1, LD1-L2 8-LD2-L1, LD2-L2 8-LD2-M 8-LD3-L, LD3-H 8-LD2 & LD3, D-500 Package	6-314x454 8-311x311 8-311x311 8-41x334 8-41x334	138 252 265 295 305	AL-14 AL-14 AL-14 AL-14	45 45 45 45 45	45 45 45 45 45	.010H Hyd Hyd Hyd Hyd	.010H Hyd Hyd Hyd Hyd	.020 .019 .019 .019	39 30 30 30 30	.035 .035 .035 .035 .035	28 65 68 68 68	634 634 634 634 634	0 to 1/P 0 to 1/P 0 to 1/P 0 to 1/P	0 to 14P2 0 to 14P2 0 to 14P2 0 to 14P2 0 to 14P2	\$ to \$ to \$ to \$ \$ to \$ \$ \$ to \$ \$ \$ \$ \$
Imperial 8-LY1-L, LY1-M, LY1-H	8-4x3}}	345	AL-14	45	45	Hyd	Hyd	.017	38	.035	6B	634	0 to 132P	C to 1/2P2	A to A
Plymouth 8-LP1-L, LP1-M, LP1-H 8-LP2-L, LP2-M, LP2-H 8-LP2-H Fury Golden Commando Package	6-31/x45/ 8-31/x3/ 8-31/x3/ 8-4/x35/	132 225 290 305	AL-14 AL-14 AL-14 AL-14	45 45 45 45	45 45 45 45	.010H .012H .012H Hyd	.010H .018H .018H Hyd	.020 .017 .017 .017	39 30 38 38	.035 .035 .038 .035	28 108 108 8B	63/2 63/2 63/2	0 to 134N 0 to 134N 0 to 134N 0 to 134N	0 to 14P2 0 to 14P2 0 to 14P2 0 to 14P2	A to A A to A A to A
FORD MOTOR CO.									1						
Edsel 8-57A, B; 58A, B; 63A, B; 64A, 76B	8-4-4 x31-2	303	Ch-18	30	45	Hvd	Hyd	.015	24	.034	78	7	14P to 114P	15P to 115P	å to 34
8-57A, 57B, 63A, 63B, 76B	8-41-x31	345	Ch-18	30	45	Hyd	Hyd	.015	27	.034	78	7	0 to 132P	0 to %P	16 to 15
Ford 8-223 cu. in, 8-292 cu. in, 8-332 cu. in, 8-332 cu. in,	6-354x322 8-354x322 8-4x322 8-4x312	145 205 240 300	Ch-18 Ch-18 Ch-18 Ch-18	45 45 30 30	45 45 45 45	.019H .019H .026H	.019H .019H .026H .026H	.025 .015 .015 .015	37 27 27 27	.034 .034 .034 .034	48 38 38 38	7°1′ 7°1′ 7°1′ 7°1′ 7°7′	14P to 114P 14P to 114P 14P to 114P 14P to 114P	14P to 114P 14P to 114P 14P to 114P 14P to 114P	1 to
Lincoln8—All	8-411x341	375	Ch-18	30	45	Hyd	Hyd	.015	27	.032	88	7°26'10"	0 to 13-5N	0 to 34P	3% to 2
Mercury 8	8 412x312 8 412x312 8 412x312	312 330 360	Ch-18 Ch-18 Ch-18	601/2 601/2 603/2	45½ 45½ 45½	Hyd Hyd Hyd	Hyd Hyd Hyd	.015 .015 .015	27 27 27	.034 .034 .034	48 48 78	7 7 7	1/2N to 2N 1/4N to 2N 1/2N to 2N	14N to 14N 14N to 14N 14N to 14N	it to it
GENERAL MOTORS CORP.															
Buick . 8-40 8-50, 60, 70, 700	8-41/(x31) 8-41/(x31)	250 300	AC-14 AG-14	45 45	45 45	Hyd Hyd	Hyd Hyd	.015	30 30	.033	58 58	7 7	NN NN	14P 14P	to to b
Cadillac 8-60, 62, 75	8-4x35/6	313	AC-14	44	44	Hyd	Hyd	.016	30	.635	56	4	34N to 134N	34N to 34P	i to i
Chevrolet	6-3 %x3 %x3 %x3 8-4 1 %x3 1 %x	145 185 250 230		31 45 45 45	46 45 45 45	Hyd Hyd Hyd Hyd	Hyd Hyd Hyd Hyd	.019 .019 .019 .018	30 30 30 29	.035 .035 .035 .035	TC 48 48 49	7% 7% 7% 7% 4	14N to 14P 14N to 14P 14N to 14P 214P	0 to 1P 0 to 1P 0 to 1P 0 to 1P	16 to 16 16 to 16 16 to 16
Oldsmobile	8 4x3+1 8-4x3+1	265 305	AC-14 AC-14	45 45	45 45	Hyd Hyd	Hyd Hyd	.016	30 30	.030	5B 5B	7 7	0 to 1N 0 to 1N	14N to 14P	0 to 1
Pontiae 8-58-25, 58-27, 58-28 8-58-25, 58-27, 58-28	8-4/4x3/4 8-4/4x3/4	240 255	AC-14 AC-14	30 30	45 45	Hyd Hyd	Hyd Hyd	.016	30	.036	6B 6E	4% 4%	0 to 1N 0 to 1N	0 to 1P 0 to 1P	0 to 1
STUDEBAKER-PACKARD CORP.															
Packard 8-57L	8-3 %x35 g	275	Ch-14	45	45	.024H	.024H	.016	31	.036	48	6	1N to 2½N	0 to 1P	1 to 5
Studebaker 6-58G 8-58B 8-58H-K7	6 3x4% 8 3 % x314 8 3 % x35 k 8 3 % x35 k	11.11													

ABBREVIATIONS

2-Left only: right, 14N to 14P.

CA - Champion or Auto-Lite.
Ch-Champion Spark Plug Co.
H-Hot.
HC-Hot or cold.

Hyd-Hydraulic valve lifters.
N-Negative.
P-Positive.
TC-Top center.

MOTOR AGE Recommends



YOUR CAR HARD TO START?

Probably you don't need a burro to get to your job but a car can be just as balky and hard-to-start. Especially in Winter. Let your friendly Automotive Serviceman check this condition now.

1957 New Passenger Car Registrations by Makes by States*

AND MONTH		Buick	Cad- illac	Chev- rolet	Chrys- ler	De Seto	Dodge	Edsel	Ford	Hud- son ^a	Lin- coin†		Metro- politan		Pack- ard	Ply- mouth	Pon- tiac	Ram- bier	Stude- baker	All Others	Total
Mabama	Sept. 9 Mos.	315 4437	76 889	1633 17784	85 980	57 647	151 1796	100	1346 16889	6 112	12 220	223 2648	9 95	263 3352	2 25	370 4770	224 2844	31 506	18 345	157 1349	5.078
Arizona	Sept.	186	95	744	75	40	107	60	854	1	19	152	8	189	2	368	161	50	24	207	3.34
	9 Mos. Sept.	1524	899 42	6449 762	544 32	280 37	794 117	60 25	6894 770	41	186	1298 134	86	1546 150	19	2380 242	1359	421 27	309 14	1069	25,958
	9 Mos. : Sept.	2053 1956	585 1601	9263 10903	387 1244	337 682	1427 2277	25 935	10033 12509	55 90	132 320	1865 1956	30 320	1985 2437	16 32	3039 4464	1813 2008	292 450	323 344	308 4780	33,958 49,308
	9 Mos.	22178	13334	92386 1110	10778	6606 45	18353 212	935	110978	958	3560 27	20175	2162	23050	346	39271 417	20940	5058 73	3722 41	36185 208	430.975
	Sept. 9 Mos.	234 2587	851	10223	926	534	1956	77	10316	22 224	276	2178	20 124	2463	77	4397	2140	956	469	1086	41.860
Connecticut	Sept. 9 Mos.	324 4026	152 1593	1434 13806	155 1765	119	363 3571	154 154	1588 15517	12 224	475	207 2450	26 218	358 3878	72	773 7577	345 4026	113 1545	74 829	540 3881	6.784
Delaware	Sept. 9 Mos.	73 911	47 388	403 3766	45 361	22 231	79 641	9	327 3677	3 26	111	86 770	5 11	87 888	13	175 1920	108	10 106	10 128	38 284	1,534
Dist. of Columbia	Sept.	79	49 604	406	48	25 330	100 975	13	405 4240	2	17	77 846	6 45	99 1260	1 25	253	141 1276	17	112	124 782	1.870
Florida	9 Mos. Sept.	1017 1089	658	4339 4310	524 409	253	591	13 170	4031	35 20	153 146	824	75	875	9	2180 1715	648	160	118	1451	17.552
Georgia	9 Mos. Sept.	9489 479	4879 192	35824 2459	2848 107	1923 93	5363 269	170	34750 2382	279	1334	6164 323	515	8128 491	105	13444 630	5825 516	1618 36	988	8263 374	141,907 8,567
daho	9 Mos. Sept.	5579	1617	24860 395	1342	808	2782 88	115	26898 275	129	391	3445 64	142	5158 98	58	6816 184	5520	630	671	1933	88,894
101	9 Mos.	1199	386	3077 8034	319	277	706	18	2894 7001	70 56	101	753	32 50	885 1881	18	1428 2808	942 1492	467 410	246 316	408 647	14,204 29,455
	Sept. 9 Mos.	2022 23756	852 8521	75607	536 7762	373 5166	991 10982	379 379	73976	982	2183	1305 13710	263	21821	340	31260	17825	5667	3670	5454	309,324
ndiana	Sept. 9 Mos.	1389 11779	370 3041	3883 32233	374 3158	294 2667	657 6075	197	4195 38025	35 424	778	742 6620	36 141	1388 9904	220	1797	1011 8057	156 1863	342 3249	286 1653	17,250 142,883
owa	Sept. 9 Mos.	484 4857	153 1158	2321 18063	144 1288	90	330 2807	143 143	2118 17555	26 244	39 296	381 3325	6 30	500 4192	7 65	707 6568	465 3726	960	80 787	109 788	8.127 67.794
Kansas	Sept.	491	136	2309	120	103	333	118	1892	33	23	339	17	478	4 58	596	458 3808	91	52 705	165 838	7,756 62,765
Kentucky	9 Mos. Sept.	4319 387	1225 86	17135 1883	1128	965 64	2470 230	118	15847 1634	235	281 21	3069 294	82 16	4137 486	3	5652 538	350	893 34	32	95	6.401
Louisiana	9 Mos. Sept.	4279 414	851 165	16031 2822	886 139	661 81	1947 208	130 126	15189 2534	86	166	2558 348	51 30	3862 541	39	5386 602	3122 505	352 40	405 51	432 149	56.413 8.794
	9 Mos. Sept.	4238 165	1294 52	23052 758	1159	811	2243 130	126	21163 738	57 11	316 22	3306 147	141	4850 144	45	6342 334	4803 223	431 84	516 54	709 143	75.602 3.131
	9 Mos.	1412	397	5319	289	334	862	17	5190	105	122	948	62	1069	21	2264	1286	704	353	910	21,664
	Sept. 9 Mos.	363 4231	143 1343	2472 19985	203 1838	92 1208	418 4208	101	1886 18562	204	31 309	261 3036	17 128	440 4491	102	1075 11025	528 4714	59 746	62 772	268 1832	8.437 78.835
Massachusetts	Sept. 9 Mos.	677 7533	255 2660	2862 25192	286 2975	208 2356	473 5041	193 193	3001 27247	37 378	83 755	466 4929	37 272	758 8582	91	1282 12687	620 6197	286 3411	85 883	631 4705	12.246
Michigan	Sept. 9 Mos.	1970	778	6882 60058	886 6191	758	1345	819	8274 73832	62	429 2145	1786 15477	89 533	2152 16994	10	3168 32887	1711 14755	232 4050	215 2046	685 5359	32,251 282,564
Minnesota	Sept.	18396 478	7754 185	2402	173	6078 131	316	819 189	2663	535 32	36	361	7	499	17	825	394	105	108	195	9,116
Mississippi	9 Mos. Sept.	6852 252	1639	22547 1492	1999	1576	3990 109	189	24313 1166	392	519 12	4549 194	49	6876 311	111	9426 380	4806 257	1965 15	1401 54	1153 50	94,352
Missouri	9 Mos. Sept.	2564 553	585 227	11154 3395	585 164	438 152	1057 456	31 124	9881	26 21	117 88	1472 420	21 24	2294 696	22 17	3438 1107	2200 691	149 106	391 123	324 214	36,719
Montana	9 Mos.	6752	2237	31379	1873	1806	4240	124	28747 485	238	499	4488	117	6828 109	111	12320	6028 84	1219	1245 41	1446	111.699
	Sept. 9 Mos.	120 1236	434	535 4236	430	24 244		15 15	4088	70	90	80 814	42	1108	24	210 1626	803	515	282	715	17.701
Nebraska	Sept. 9 Mos.	229 2507	72 623	1105 9144	627	38 312	130 1023	45 45	1139 9307	10 105	15 133	211 1746	14	235 1968	45	394 2896	172 1622	35 425	389	341	3.933
Nevada	Sept. 9 Mas.	22 415	15 223	76 1513	13	131	7	12000	127 1594	1 3	92	34 426	16	39 562	14	37 533	26 499	32	143	21 562	7.099
New Hampshire	Sept. 9 Mas.	83	32	410	30	16	57	21	393	8	7	86	4	73	10	161	79 855	40	26 258	120 799	1,626
New Jersey	Sept.	790 834	259 641	3478 3586	249 691	220 449	1002	21 346	3190 4034	61 30	85 121	613 673	45 43	717 1080	14	1448 2238	872	484 138	175	707	17.674
New Mexico	9 Mos. Sept.	10411	5147 49	35804 712	6721 45	4955 37	9900	346 29	37265 543	348	1280	7384 112	294 10	10298	243	21827 193	8673 110	2190 25	2091	4766 79	169,943
New York	9 Mos. Sent.	1272 2413	394 1334	5425 9847	449 1393	315 916	800 2396	29 639	4900 9688	36 71	108	962 1991	50 109	1234 2855	18 38	1593 5098	1199 2355	236 443	223 439	578 2419	19,819
North Carolina	9 Mos.	28946	12129	88598	15323	10384	24229	639	92892	999	3176	20310	802	29409	444	49673	23278	6487	4416	17674	429,808
	Sept. 9 Mos.	635 5521	176 1439	2472 18862	174 1403	109 1060		65 65	2450 21905	11	31 300	328 2899	16 128	586 4741	58	843 6712	457 4131	73 758	76 736	138 907	8,928 74,224
North Daketa	Sept. 9 Mes.	901	28 234	628 4582	62 407	25 274	92 759	16 16	681 4568	85 85	14 87	71 784	16	124 1058	21	200 1495	94 659	32 359	35 235	19 173	2.225
Ohio	Sept. 9 Mos.	1943 21932	592 6263	6958 64383	777 7544	558 6240	1774	712 712	7513 74588	56 769	159 1693	1580 15451	63 438	1923 19048	21 310	3160 34124	1771 17553	228 3253	234 2847	541 4309	30,563 298,942
Oklahoma	Sept.	406	120	1634	76	63	210	42	1638	12	8	278	14	421	3	467	361	54	59 455	131	5,997
Oregen	9 Mos. Sept.	3368 256	1124 81	13897 1398	712 114	696 84	1742 212	42 112	14233	106	210 25	2528 199	65 20	3414 279	41	4701 409	2767 243	595 95	79	527	5.272
Pennsylvania	9 Mos. Sept.	2930 2028	904 738	12171 6923	944 832	943 648	2034 1558	112 257	11488 5737	173 82	331 131	2258 1379	190	1684	63 28	4063 4208	2605 1648	1194 306	733 358	994	49,266
Rhode Island	9 Mos. Sept.	20466	6550 54	64541 423	8823	7101		257	59425 610	1071	1697	13805	389			39281 250	16348	4188		6529	288,225
South Carolina	9 Mes.	1025	463	3795 996	507	333	784	2	4839	126	122	581	54	1184	25	2098	822	529	161	897	18,327
	Sept. 9 Mos.	276 3022	72 687	9652	52 528	51 470		57 57	909 10852	41	102		8	2010	17	307 3471	192 1956	208	31 322	124 601	36.523
South Dakota	Sept. 9 Mos.	78 1071	22 240	470 4393	31 272	16 227	76 670	17 17	500 4448	7 75	68 68	94 684	5	89 942	20	128 1423	71 767	25 366	31 271	175	1,691
Tennessee	Sept. 9 Mos.	393 5272	128 1116	1818 18327	96 1007	86 842	234 2567	113	1796 19343	10 133	18 235	296	10	379 3983	2	568 6133	382 3822	35 624	50	114 606	6,521 67,810
Texas	Sept.	1503	551	8097	543	333	829	395	7509	22	89	1296	88	1835	11	2722	1440	129	139	661	28,177
Utah	9 Mos. Sept. 9 Mos.	17549 124	5572 38	76218 397	4885 58	3165 45	93	24	74753 440		1056	102		147	1	24911 167	13798	1889	18	113	268,437 1,897
Vermont	9 Mos. Sept.	1332 65		3811 257	468 24	459 13		24	4391 282	66 7	132	1049		1284 54	19	1781 95	1093	291 26	202 25	754 77	18.27
Virginia	9 Mos.	729	168	2577	186	109	420	5	2573	57	44 35	409	53	498		991 1195	588 702	355	188	671	10,63
	Sept. 9 Mos.	556 5720	1537		184 1755	158 1454	3297	110	22830	187	387	4223	190	4522		9629	5789	1058	896	2429	89,13
Washington	Sept. 9 Mos.	353 3242		1783 13772		110 874	364 2544	71	1623 13868	29 256	44 304		346			654 4945	358 2785	1828		676 3956	7,22 56,14
West Virginia	Sept. 9 Mos.	329 3034	69	1301	107	83 657	221	53	1093	8 98	14	201	1 3	256		513	288	33 463	68	97	4,74
Wisconsin	Sept.	722	205	2614	227	132	430	153	2681	66	42	482	15	767	7	829	547	212	111	194	10.43
Wyoming	9 Mos. Sept.	8282	23	252	19	20	47	24	232	4	4	54	1 3	65	2	91	60	18	8	32	1.02
	9 Mes.	777	222	-		-	-				-			-							9,46
Total Septemb	er, 1957 er, 1956	28323 40604				7901 6960			121154 87282			21880									495,21 421,02
Total 9 Mont	hs. 1957	307718		1098773	-		204896		1145985	-		212872	-	286697	-	480176			48254	139089	-
Total 9 Mont			109910						1010736	1 = 000			513			377632					4,612,82

^{*} Data from R. L Polk & Co.

CURRENT PASSENGER CAR PRICE, WEIGHT AND BODY TABLE

Following are prices at factory for cars with standard equipment as of November 25, 1957 State or local taxes, transportation and finance charges and optional equipment are extra.

BODY MAKE AND MODEL	List Price Factory without Federal Taxes	Federal Taxes and Mandling Charges		Shipping Weight	BODY MAKE AND MODEL	List Price at Factory without Foderal Taxes	Federal Taxes and Handling Charges	Suggested Price at Factory including Federal Taxes	Shipping Weight	BODY MAKE AND MODEL	List Price at Factory without Federal Taxes	Federal Taxes and Handling Charges	Suggested Price at Factory including Federal Taxes	Shipping Weight	BODY MAKE AND MODEL	List Price at Factory without Federal Taxes	Federal Taxes and Handling Charges	Suggested Price at Factory including Federal Taxes	Shipping Weight
AMERICAN				P.	CHRYSLER (CORP		nt'd		FORD MOTO						иото		cont'	d
De Luxe 6 Sedan, 4d Super 6 Sedan, 4d H. T. Sedan, 4d Sta. Wagen, 4d			2047 2212 2287 2506	2947 2960 2963 3069	Sta. Wagons Suburban, 2d Sierra, 2s Sierra, 3s Cus. Sierra, 2s Cus. Sierra, 3s	2715 2775 2907 2940 3072	215 220 230 232 242	2930 2995 3137 3172 3314	3875 3930 3990 3955 4035	FORD, Cent'd Fairtane 506 Club Sedan Town Sedan Club Victoria Town Victoria Sunliner	2289 2339 2345 2405 2546	184 188 189 193 203	2473 2527 2534 2598 2749	3454 3256 3464 3561 3830	GADILLAC, Cen Sedan de Ville Convertible Biarritz Seville Series 00 Special Sedan	5040 5000 6910 8910	457 454 590 590	5497 5454 7500 7500 8232	4855 4845 5070 4810
Gustom 6 Sedan, 4d			2327	2966	Cus. sierra, si	-	242	3314	1030	Skyliner Sta, Wags, V8	2907	231	3138	4069	Series 75 Sedan	7750	710	8460	538
Sta. Wagon, 4d Rebel, Sup. V8 Sedan, 4d Sta. Wagon, 4d			2621 2342 2636	3079 3300 3410	IMPERIAL Imperial Southampt., 26	4417	347	4764	4640	Ranch Wag., 2d Ranch Wag., 4d Del Rio Wagen Ctry, Sed., 8p.	2392 2442	195 190 193 197	2479 2533 2585 2639	3620 3677 3625 3682	Imperial Elde, Breugh'm.	7950	725	8675 13074	542
Rebel, Cus. V8 Sedan, 4d H. T. Sedan, 4d Sta. Wagon, 4d			2457 2532 2751	3313 3328 3418	Southampt., 4d Sedan, 4d Crown Southampt., 2d	4516 4516 4928	354 354 385	4870 4870 5313	4795 4590 4730	Ctry, Sed., 9p. Country Squire Thunderbird Tudor	2542 2663	204 213	2748 2876	3750 3787	Delray V8 Utility Sed., 2d Sedan, 2d	1924 2005	196 203	2120 2208	335 331
Amb. Sup. V8 Sedan, 4d Sta. Wagon, 4d Amb. Cus. V8			2587 2881	3456 3544	Southampt., 4d Sedan, 4d Cenv. Coupe Le Baren	5155 5155 5273	402 402 411	5557 5557 5684	4915 4755 4820	LINCOLN Capri			111211		Sta. Wagon, 2d Sta. Wagon, 4d Biscayne V8	2055 2294 2344	207 226 230	2262 2520 2574	344 306 374
Sedan, 4d H. T. Sedan, 4d Sta. Wagon, 4d H.T.St. Wag.,4d			2732 2822 3026 3116	3462 3475 3568 3586	Sedan, 4d Southampt., 4d	5468 5468 14019	426 426 961	5894 5894 15000	4780 4940 5960	Hardtop, 2d Sedan, 4d Hardtop, 4d Premiere	4415 4553 4553			4735 4810	Sedan, 2d Sedan, 4d Sta. Wag., 4d, 6p. Sta. Wag., 4d, 9p.	2131 2181 2441 2541	212 216 237 244	2343 2397 2678 2785	346 345 375 383
HRYSLER	CORR				PLYMOUTH*					Hardtop, 2d Sedan, 4d Hardtop, 2d Continental	4894 5124 5124		******	4820 4880	Bel Air V8 Sedan, 2d Sedan, 4d Sport Coupe	2270 2320 2326	223 227 228	2493 2547 2554	343 343 343
HRYSLER Windser	LORI				Piaza V8 Bus. Coupe	1943	158	2101	3320	Coupe, 2d Sedan, 4d	5367 5597 5597			4865 4865	Sport Sedan Ht. Impaia, 2d.	2386 2456	232 237	2618 2693	35
Sedan, 4d Hardtop, 2d Hardtop, 4d Twn. & Ctry, 2s Twn. & Ctry, 3s	2849 2928 2988 3302	228 231 238 250	3074 3159 3224 3561	3895 3860 3815	Club Sedan Sedan, 4d Savey V8 Club Sedan Sedan, 4d	2026 2074 2153 2200	164 168 174 178	2190 2242 2327 2378	3315 3415 3380 3400	Hardtap, 4d Convertible MERCURY Menterey	5792			5040	Impal. Conv., 2d Sta. Wag., 4d, 6p. Corvette		248 248 296	2841 2835 3631	35 37 27
Fwn. & Ctry, 3s Saratoga Sedan, 4d	3476	272	3748 3758	4245	Sport Coupe Sport Sedan Belvedere V8	2222 2288	179 184	2401 2472	3400 3475	Sedan, 2d Sedan, 4d Hardton, 2d	2422 2487 2532			4880 4150 4075	OLDSMOBILE Series 88 Sedan, 2d	2514			38
Hardtop, 2d Hardtop, 4d New Yorker Sedan, 4d	3541 3613 3923	277 282 367	3818 3895 4230	4045 4145 4195	Club Sedan Sedan, 4d Sport Coupe	2278 2325 2341	183 187 188	2461 2512 2529	3370 3430 3410	Hardtop, 4d Convertible Montclair	2598 2822			4150 4225 4155	Sedan, 4d Holiday Coupe Holiday Sedan	2574 2627 2699			31 35 46 46
Hardtop, 2d Hardtop, 4d Conv. Coupe	3971 4024 4356	311 315 340 347	4282 4339 4696 4863	4205 4240 4350	Sport Sedan Conv. Coupe Suburban V8 Deluxe, 2d	2407 2525 2318	193 202 186	2500 2727 2504	3520 3545 3645	Sedan, 4d Hardtop, 2d Hardtop, 4d Topk. Cruis., 2d				4085 4165 4150	Conv. Coupe Fiesta Sedan Ht. Fiesta	2931 2990 3083		1 10000	42
Twn. & Ctry., 2s Twn. & Ctry., 3s 300D Hardtop, 2d	4656 4740	362 368	5018	4445 4305	Cust., 4d, 6 p. Cust., 4d, 9 p. Sport., 4d, 6 p.	2431 2481 2611 2623	195 199 209 210	2626 2680 2820 2833	3690 3755 3840 3745	Convertible Tnpk, Cruis., 4d Park Lane Hardtop, 2d	3555			4295 4230 4280	Super 88 Sedan, 4d Holiday Coupe. Holiday Sedan.	2821 2960 3032	1407		39 39 40
Conv. Coupe	5140	398	5538		Sport., 4d, 9 p Fury V8 Sport Coupe	2753 2808	220	2973 3032	3830 3510	Hardten, 4d Convertible Sta. Wagons Comtr., 2d, 8p.	3826 3788 2778		173141	4390 4405 4400	Conv. Coupe Ht. Fiesta Series 98	3296 3296			40
Firesweep Sedan, 4d Sportsman, 2d Sportsman, 4d Conv. Coupe Sta. Wagen, 2s	2567 2633 2692 2939 2983	207 212 216 235 238	2774 2845 2908 3174 3221	3860 3860 3720 3850 3955	FORD MOT	OR C	ю.			Comtr., 4d, 6p. Comtr., 4d, 9p. Voyager, 2d, 6p. Voyager, 4d, 5p. Col. Pk., 4d, 6p.	2843 2932 3243			4485 4805 4435 4525 4540	Sodan, 4d Heliday Coupe. Heliday Sedan. Conv. Coupe	3473 3655 3726 3915			43 42 43 43
Sta. Wagon, 3s Firedome Sedan, 4d	3115 2810 2896	248 225 232	3363 3035 3128	3960 3965 3825	EDSEL Ranger Sedan, 2d	2300 2366			3729 3805	GENERAL I	иотс	RS (CORF		PONTIAC Chieftain Sedan, 2d Sedan, 4d	2284 2343		11-11	36
Sportsman, 2d Sportsman, 4d Conv. Coupe Fireflite	2949 3185	236 254	3185 3439	3910 4065	Sedan, 4d Hardtop, 2d Hardtop, 4d Pacer	2367 2448			3724 3796	BUICK Special 40 Sedan, 2d	2388			4063	Catal., Coupe Catal., Sed., 4d Safari, 4d, 3s Super Chief	2345 2424 2637			31 37 40
Sedan, 4d Sportsman, 2d Sportsman, 4d Conv. Coupe Sta. Wagon, 2s	3268 3384 3406 3630 3684	260 266 270 287	3528 3620 3676 3917 3975	3990 3920 3940 4105	Sedan, 4d Hardtep, 2d Hardtep, 4d Convertible	2499 2564 2618 2771			3857 3773 3857 3909	Sedan, 4d Hardtop, 2d Hardtop, 4d Cenv. Coupe Est. Wagen, 4d	2448 2489 2568 2786 2862			4115 4058 4180 4185 4396	Sedan, 4d Catal. Coupe Catal., Sed., 4d Star Chief	2420 2486 2540	111-0		37 38 38
Sta. Wagen, 3s Adventurer Sportsman, 2d	3816	291 301 294	4117	4225 4295	Corsair Hardtop, 2d Hardtop, 4d Citation	3066 3139 3242			4134 4235 4136	Ht. E. Wag., 4d Century 80 Sedan, 4d Hardtop, 2d	2974 3007 3056			4408 4241 4182	Sedan, 4d Catal. Coupe Catal. Sed., 4d.	2636 2640 2709	1111		38 37 38
Conv. Coupe	3999	315	4314		Hardtop, 2d Hardtop, 4d Convertible Sta. Wagens Roundup, 2d	3316 3489 2630			4230 4311 3761	Hardtop, 4d Cenv. Coupe Ht. E. Wag., 4d Super 80	3119 3346 3487			4267 4302 4570	STDE-PACK PACKARD Hawk	. co	RP.	3995	35
Coronet 8 Club Sedan Sedan, 4d Coronet V8	2238 2310	179 185	2414 2495	3360 3410	Villager, 4d, 5p. Villager, 4d, 9p. Bermuda, 4d, 5p.	2683 2736 2922			3827 3900 3853	Hardtop, 2d Hardtop, 4d Readmaster 75	3308 3443			4392 4500	STUDEBAKER Scotsman Sedan, 2d			1795	26
Club Sedan Sedan, 4d Lancer, 2d Lancer, 4d	2335 2410 2449 2528	186 192 195 201	2521 2602 2644 2729	3505 3555 3540 3905	Bermuda, 4d, 9p.	2975	-		3919	Hardtop, 2d Hardtop, 4d Conv. Coupe Limited 700	4149 4251 4263			4568 4668 4676	Sedan, 4d Sta. Wagen, 4d Champion Sedan, 2d			1874 2055 2189	21
Convertible Royal V8 Sedan, 4d Lancer, 2d	2693 2554 2607	214 203 207	2907 2757 2814	3725 3570 3565	Custom V8 Bus, Tuder Tuder Sedan	1923 2004	158 163	2167	3283 3306	Hardtop, 2d Hardtop, 4d Conv. Coupe	4549 4851 4863			4603 4710 4691	Sedan, 4d Commander Sedan, 4d Sta. Wagen, 4d			2253 2378 2644	33
Lancer, 4d Cus. Rey. V8 Sedan, 4d Lancer, 2d	2664 2766 2864	211 219 222	2875 2985 3026	3640 3640 3610	Forder Sedan Fairlane V8 Club Sedan Town Sedan	2054 2147 2197	167 173 177	2221 2320 2374	3334 3431 3483	Series 82 Coupe Sedan	4375 4475	409 416	4784 4891	4630 4675	President Sedan, 4d Hawk Silver, 6 cyl.			2639 2219	31
Lancer, 4d Convertible	2870 3015	227 238	3097	3670 3785	Club Victoria Town Victoria	2271 2332	182 185	2453	3429 3506	Ext. Sedan Coupe de Ville	4650 4810	429 441	5079	4778 4705	Silver, 8 cyl Golden			2352 3282	

Prices of 6 cyl. models are \$137 less than 8 cyl. models for the Custem; \$124 for the Fairlanes and \$107 for the Station Wagons.

^{*} Prices of 6 cyl. models are \$100 less than 8 cyl. models.





Reworked Connecting Rod
Helps Remove Stuck Lifters

KINK OF THE MONTH

APPROX. .060 IN. THICK

TAPERED TO \$16 IN.

4 ½ IN.

I have made a tool to remove varnished or stuck hydraulic lifters from 1953-57 Cadillacs. 1953-57 V-8 Buicks, 1955-57 V-8 Pontiacs, 1955-57 V-8 Chevrolets and 1949-57 V-8 Oldsmobiles. The tool is made from a connecting rod from a 1946-47 Series 40 Buick. A section approximately 6 inches long is cut from the rod, and trimmed down by grinder and file to listed dimensions. The tool gives a firm grip that will not slip on a varnished or stock lifter and they can be removed by a twisting pulling motion. Rolof Smith, Shop Foreman, Mid-West Motors, Ltd., Rose St. & 12th Ave., Regina, Sask., Canada.

Cure For Noisy Mercury Speedometer

The tape drum in the 1957 Mercury speedometer is quite noisy because too much slack is left on the drum shaft. These noises can be quickly eliminated by removing the drum mounting plates and filing the two upright plate posts down until the slack is all gone in the drum shaft. Be careful to leave it just loose enough to allow the drum to turn freely. Andy Sarratt, Manager, Parts Dept., Hailey Motor Co., 313 So. Second St., Rogers, Arkansas.


Heater Hose Used Over Battery Cable Ends

When removing a starter, solenoid or any time the battery cable has to be removed, I find a piece of heater hose 2 inches long very useful. Slip the hose over the cable end. This prevents a short circuit and is quicker than removing the battery cable at the battery. A. G. Wester-Mark, Service Manager, New Devon Motors, Box #318, Devon, Alberta, Canada.

Installing Stop Light Switches on Cadillacs

I have been having trouble installing stop light switches on 54, 55, 56 Cadillacs and Chevrolets. It has always taken 2

STERDAY.



when compression ratios were 3 to 1, any good oil ring would do...as in this rakish Apperson Jack Rabbit, vintage 1907. Guaranteed to turn up 75 miles per hour, the car featured 60 H.P. engine, 4speed selective type transmission, double ignition with magneto and coil, and carried a price tag of \$5,000.



The Perfect Circle Type "98" Chrome oil ring was specifically designed to meet the exacting demands of today's high-compression engines. Featuring universal applica-Mills, Ont.

chrome oil ring!

tion, bottomless and conventional grooves, all depths, the PC Type "98" oil ring was the first to have a patented side-sealing action with multiple tiny springs that exert both side and radial pressure. And of utmost importance, Type "98" Chrome Oil Rings provide maximum oil drainage! Perfect Circle Corporation, Hagerstown, Ind.: The Perfect Circle Co., Ltd., 888 Don Mills Road, Don

PERFECT CIRCLE

PISTON RINGS


Preferred by more people than any other brand!

a seat and cannot jump away when pressure is applied. The notch enables the rod to be lined

men to put them on. I have found an easy way to put them on. It takes me about 30 minutes to install one now. I just put a 3/16 stove bolt 2 inches long with the head removed in the screw hole of the switch. Then I put switch up through the hole of the floor board from under hood. Brake pedal can be pushed down if there is not enough room to work. When stove bolt is through hole you can see other hole of switch. Start screw in hole, bolt from inside of car. Then take out stove bolt and put in other screw. John H. Walter, Norton Tire Co., Inc., 1454 Alton Road, Miami Beach, Fla.

Tricky Method For Bleeding Brakes

Several cars have the master cylinder in hard to reach locations and it is practically impossible to hook up the bleeder tank. These jobs can be easily bled and filled, without touching master cylinder filler plug, by doing the following. Using an old bleeder valve of the right size for wheel cylinder, solder or braze a fitting to take bleeder tank hose. Drill a 1/16 inch hole through the valve. Remove bleeder valve from wheel cylinder nearest master cylinder (usually left front) and hook up bleeder tank, but do not turn on pressure. Then follow these steps in order: (1) Block pedal



about 1½ inches with pedal jack, to seal off compensating port, and turn on bleeder tank pressure. (2) Starting with wheel cylinder farthest from master cylinder, bleed the three wheels

which are not hooked up to the bleeder tank. (3) When the three wheels are done, release pedal jack and let fluid run into master cylinder until it comes out the vent hole in filler plug. This fills the master cylinder and at the same time carries off any air left in left front line. (4) Shut off pressure and remove bleeder tank and fitting. Replace original bleeder valve and close as soon as possible. (5) Apply pedal jack with medium pressure and slowly open left front bleeder valve to expel any air that may have entered left front cylinder when tank was removed. Close valve tightly and job is completed. John C. Mucciaro, Johnnie's Auto Repair, 5538 Monte Vista, Los Angeles 42. California.

Reworked Push Rod Installs Detent Ball

We have found an easy way to install the ball bearing for the manual control valve detent lever on Ford - O - Matic transmissions. This works especially well when replacing it without removing the transmission from the car. We used a valve push rod from an overhead valve motor, ground off the top and sides and notched it to fit over the lever. This way the ball sits in



up with the angle of the hole. Donald Solt, Red Hill Garage Inc., Red Hill, Pa.

How To Overcome Oil Leak At Valve Cover

Some older model Chevrolet motors leak oil at the valve cover, due to the cover spreading in the middle. We overcome this by making a paper templet and cutting a horseshoe shaped piece of 3/16 inch plate. They also seem to be short at the backend or I should say they do not get a good bite on the gasket at the rear. The gasket rolls up under impact or pressure resulting in oil leaks. They are also very messy and not very economical to operate either. Neil Leadger, Watson's Service, Savona, B. C.

If you have an original idea for a special tool, a short cut on a job or any trick of value to others, write it down and if necessary make a rough sketch. Just make it clear. Send it to Motor Age. If your Kink is used it may bring you \$7.50 or \$25. All entries become the property of the Chilton Company. Because of the quantity of entries sent in, none can be returned.

Over 30,000 Visymmetric Owners

TELL YOU THIS IS THE WAY TO MAKE MONEY WITH IGNITION!

ECHLIN Visumatic Selling and Service gives you a fast moving, perpetually balanced Ignition stock, plus visual stock control and freedom from obsolescence. You choose a single Visumatic Shelf Assortment, Counter Cabinet, Wall Rack or Floor Cabinet, and also select the Ignition stock that best suits your individual needs.

NAPA Jobbers stock Visumatic Displays and famous ECHLIN Ignition Parts. Call your NAPA Jobber today-let him show



VISUAL STOCK CONTROL BALANCED STOCK FREEDOM FROM OBSOLESCENCE

ELECTRICAL PARTS



Officers for the coming year of IGO of Ohio are shown at left. Standing, left to right, are Harold Grindle, executive director of the Association; Lloyd Wilson, 2nd vice president; Samuel Martin, 3rd vice president; and Robert Straub, secretary-treasurer. Seated at table is Frank Hornyak (left) who was re-elected as president. Seated next to Frank is William Good, 1st vice president by re-election.



Record Attempt

Roy Leslie failed to crack his own record by about 2 mph late in August at the 9th annual Bonneville Speed Trials. His Kenz-Leslie Streamliner was clocked at 253.92 mph. Kenz-Leslie V-8 Service is a member of IGO of Denver; Mr. Wm. Kenz is a member of the Denver chapter's board of directors.

Aspiration plus perspiration enables a man to reach his goal.

Full House . . .

FOR CHANNELLOCK

PLIERS

Continued from Page 37

two weeks vacation at the radiator repair manufacturer's school, and now happily combines his regular repair business with radiator repairing. And much of his radiator work finds its way from surrounding car dealerships.

George is now producing good work and there is evidence that, at the end of his first year, he will own his equipment. Thus, for his ingenuity and time, George Bingham has eliminated a depressing period of today's business—under-work.



CHAMPION DEARMENT TOOL COMPANY . MEADVILLE, PA.

Look for the trademark

on the bandle

Schrader

is the word for air...in full tubeless tire repair and maintenance service



Gauges, tools, replacement valves, valve cores, valve caps-everything you need from Schrader.

Tubeless business—changeover, repair, replacement—grows every day as tubeless tires roll up the mileage. Be sure you have complete Schrader service for the quickest, best way to handle this new business. Your Schrader supplier has everything you need to protect your customers and to protect your reputation for handling first quality brand name products. And remember, the valve should be as new as the tire to assure the full mileage built into the tire.



A. SCHRADER'S SON . BROOKLYN 38, N. Y.
Division of Scovill Manufacturing Company, Incorporated

FIRST NAME IN TIRE VALVES

FOR ORIGINAL EQUIPMENT AND REPLACEMENT

Torque ratings are 250 foot pounds for the light-duty truck V-8 engine at 2800 revolutions per minute. The V-8 engine is rated at 288 foot pounds of torque at 2600 revolutions per minute. Compression ratio for all Studebaker truck engines this year is 7.5 to 1.

In the light-duty line, wheel-bases of 112-122, and 131 inches will be available with gross vehicle weight ratings from 4,800 pounds in the half-ton model to 10,000 pounds in the one-ton model. Pick-up bodies will be $6\frac{1}{2}$ to 9 feet in length and stake and platform types will be 8 and

9 feet. The all-steel, double wall, pick-up body will be retained. The pick-up again will have wider clear floor space—51½ inches wide. A four-speed synchromesh transmission will be standard on the one-ton, and Studebaker's automatic transmission will be optional on this model.

Medium-Duty Trucks


In the medium-duty line of one-and-a-half-ton and two-ton trucks, four wheelbases will be available ranging up to 195 inches for the two-ton model. The 195-inch wheelbase is designed to accommodate 16- to 18-foot vans, stakes or special bodies. Other models include factory installed 9-foot through 14-foot stake and platform bodies. For greater payload capacities, gross vehicle weights on the two-ton models are 16,500 pounds on the 155-inch wheelbase model and 17,000 pounds on both the 171-inch and 195-inch wheelbase models.

In the heavy-duty line there will be four chassis and cab models. Factory installed platform-stake bodies will be available in 9, 12, and 14-foot lengths. Wheelbases of 131, 155, 171 and 195 inches will be used. Gross vehicle weights are 18,000-19,000 pounds. The power train will include the 289-cubic-inch V-8 engine, four-speed heavy-duty synchromesh transmission, and an 11-inch clutch.

Heavy-Duty Front Axles

Heavy-duty front axles with a carrying capacity of 5,000 pounds and rear axles with a carrying capacity of 15,000 pounds will be used with these new units. A 6.8 to 1 rear axle ratio will be standard with a 6.2 to 1 ratio optional at no extra cost for higher road speed and greater economy. Two-speed rear axles with electric shift will also be available. The new trucks

(Continued on page 76)



for trucks, busses, cars!

- ★ Operates independently of engine to assure positive flow of gas—always!
- ★ No bellows or rocker arms to wear!
- ★ Heavy-duty construction. Weatherized finish, in bright green baked enamel.
- ★ Models with single or dual pumps!
- ★ Pump may be mounted under hood, on fire wall or fender panel, or on frame near gas tank.

STEWART-WARDER

Instrument Division, Dept. AD-127 1840 Diversey Parkway, Chicago 14, Illinois



for modernization..that pays off

the NEW Ingersoll-Rand

Channel Ho

...a motorcompressor designed to meet the specific needs of today's modern service station and repair shop.

it's compact

A Channel-flo requires less than half the installation space of a tank-mounted, belt-driven compressor of comparable size.

it's efficient

Balanced opposed-piston construction with the timetested I-R Channel Valve means better performance with greater economy. The compressor is mounted directly on the motor shaft, completely eliminating main bearings.

it's modern

There are no belts or couplings so a guard is not required. The new Channel-flo is safe, reliable and completely new.


it's economical

Moderate first cost, minimum maintenance, low-cost operation, continuous service rating . . . are just some of the reasons why the I-R Channel-flo should be your top choice for a dependable air supply.



Get in touch with your local Ingersoll-Rand Jobber or write direct to Ingersoll-Rand for complete data on the powerful new Channel-flo. Available in 1½ or 2 hp sizes—Two stage—rated 200#

Ingersoll-Rand



will have three-stage rear springs rated up to 7,300 pounds, and will be equipped with heavyduty six-stud wheels.

A special "premium engine package" including many of the standard heavy-duty features of the big 289-cubic inch engine will be available with the 245cubic inch six-cylinder engine or the 259-cubic inch V-8. The package includes heavy-duty inlet and exhaust valves, heavyduty exhaust valve springs, and rotary cap kit, chrome-plated top compression piston rings and, on the 259-cubic inch engine, heavy-duty aluminum timing gear, heavy-duty connecting rod bearings and crankshaft bearings, and a one-quart oil bath air cleaner.

A little white lie travels a mighty short distance before it gets a black eye.

GMC

Continued from Page 46

ing distance on the right hand side of the road, perfect focus on both upper and lower beams, reduction of high contrast areas and less interference with oncoming drivers in the low beam.

Stronger Frames

A heavier, stronger front frame cross member provides greater frame rigidity and minimizes front end flexing on all GMC models from the 100 series on through the model 370. A new bulkhead type radiator mounting has the radiator core bolted directly to the radiator support tie bar and side baffle assembly which in turn is springmounted to a frame bracket for more rigidity.

Six-wheel models with heattreated frame rails for 1958 have a high tensile steel reinforcement at the bogic cross member, which replaces a mild steel reinforcement, to give longer life to the frame.

Exhaust and vibration noises will be reduced as a result of new flexible muffler and tail pipe mountings on GMC models 100 through 250. Bendix power steering units are available on models 350 and up, a change from former power steering units to give smoother steering.

On GMC models 100 and 100-8 a Powr-LOK differential which permits the rear axle to send the greatest driving force to the wheel that has the best traction will be offered.



Today, engines differ greatly! Each requires special tools and specialized technical knowledge for proper servicing. The lubrication of these engines is just as specialized. That's why there are Kendall Motor Oils for every type of engine and service. All offer the natural superiority of 100% Bradford Pennsylvania Crude Oil — world's richest. By using the proper Kendall Motor Oil for the type of engine design and service, you develop more satisfied customers and steadily step up your volume and profits.

KENDALL REFINING COMPANY BRADFORD, PENNA.

Lubrication Specialists since 1881

O MYSTERY - JUST BIG RETURNS vith these ic Transmission Tools

It's so easy, any mechanic can handle automatic transmission adjustments with these Snap-on sets. The tools make this work as simple as a brake adjustment job.


And the returns are big! All over the country, sets like these have paid for themselves in short order. You can adjust practically any automatic transmission; many jobs take only a half hour or less. And a properly adjusted automatic transmission means big savings and greater satisfaction for the car or truck owner.


These valuable income boosters can be yours on easy payments. Ask your Snap-on man for full details or write us.

Automatic Transmission Tool Set 2028-ATS

This set handles band and linkage adjustments on Hydramatic, Dynaflow, Powerglide, Fordomatic, Mercomatic, Flightomatic, Powerflite, and Turbodrive transmissions. It's quick and profitable because an estimated 70-75 percent of all adjustments can be done externally, without removing transmission. Photographs and easy-tounderstand instructions in Snap-on instruction book make the job extra simple.







On transmission overhaul, gauge localizes trouble area; spots oil leaks, pressure leaks, faulty servo pistons, clogged screens. Use it on Dynaflow, Flightomatic, Fordomatic, Hydramatic, Mercomatic, Powerflite, Powerglide, Studebaker, Turbodrive and Ultramatic transmissions.

*Snap-on is the trademark of Snap-on Tools Corporation



SNAP-ON TOOLS CORPORATION



models and the P400 forward-control model. Maximum gross vehicle weights will span 5,100 to 46,000 lbs. Gross combination weights, advanced as much as 10,000 lbs on tandem models, will range up to 65,000 lbs.

Light and medium-duty trucks will be different in ap-

pearance from heavy-duty models. This has been accomplished with two new grille designs. A bright, chrome-trim package is offered for a distinctive flavor. A full-width alligator hood, heavy-duty bumpers, and twin headlights will be carried on all models. Dodge engineers claim


the full-width hood will provide easy engine accessibility. The hood reportedly swings upright to a full 90 deg.

A new four-wheel drive model, the W300 Power wagon, will be offered in pick-up, stake, chassis and cab, and chassis and cowl models. A panel truck has also been added to the W100 models.

New Safety Features

Turning to safety, new hydraulic brakes have been added to medium and high-tonnage models. This has caused brake lining areas to increase as much as 152-sq. in. Power brakes will, of course, be standard for all trucks. Dodge has installed a full traction differential in its D100 models. Engineers assure better traction over slick surfaces with the addition.

Night driving has been facilitated with dual headlights and the adoption of nine light body colors, some in discerning two-tone combinations. Dodge engineers have mounted the gas tank beneath the cab away from the driver. According to Dodge, cabs will be more comfortable on '58 models. A new transistorized radio has been installed between the sun visors, enabling the driver to change the dial without lowering his eyes.




We saved on initial costs . . . are saving mechanics' time, says Motor Co. President

Harr Motor Company, Ford Dealer in Worcester, Mass., installed versatile, profitable Joyce Lifts throughout. President Leo W. Malboeuf states:

"We were fortunate in having a qualified supplier who helped us select the right Joyce Lift Model for each of our departmentalized service stalls; saving hundreds of dollars in acquisition costs and providing obvious savings in mechanics' time."

Leo W. mallouf



- HIGH WORKING CAPACITY IMPROVED CUSTOMER RELATIONS
- FAMOUS JOYCE JACKING UNIT FAST CAR AND TRUCK SPOTTING
 MAXIMUM UNDER-CAR ACCESSIBILITY



JOYCE SINGLE POST H-MASTER LIFT

JOYCE TWO POST TWIN-MASTER FRAME LIFT



JOYCE TWO POST SHOPMASTER LIFT • • • THE MECHANICS LIFT JOYCE TWO POST COMBINATION AUTO, LIGHT TRUCK LIFT (not illus.)



JOYCE TWO POST HEAVY DUTY COMBINATION BUS AND TRUCK LIFT

JOYCE G

Write today for a free copy of Bulletin 139-L . . . find out how Joyce Lifts can be profitable for you!

THE JOYCE-CRIDLAND COMPANY
Designers and builders of lifting equipment since 1873
U.S.A.: 2027 E. FIRST STREET, DAYTON 3, OHIO
Canada: Midland Toundry & Machine Co., Ltd., Midland, Ont.







WIX-O-MATIC

The money-making Oil Filter Service Plan that is revolutionizing Oil Filter Cartridge sales! Makes service quick and profitable—the right Cartridge, always at your fingertips. GUARANTEED SALES—with minimum, controlled inventory. You can have WIX-O-MATIC—FREE! Ask for details.

... and YOU'RE going
RIGHT for PROFITS with WIX!



Original Equipment on America's Leading Cars

Easy, twist-of-the-wrist installation and removal. Selfcontained unit with built-in relief valve, gasket, and antidrainback valve. There's a WIX Oil Filter Cartridge engineered for every car and truck on the road—and when you have the exclusive WIX-O-MATIC selling and service plan going for you, you're in the money! You select the exactly balanced stock that's right for you—and your sales are GUARANTEED!

You get a good deal with WIX - top-quality Filter Cartridges, profitactive selling aids, and the hi-impact of LIFE and SATURDAY EVE-NING POST advertising that pre-sells WIX! to your customers.

Get the whole WIX story - you'll be amazed what WIX can do for you - and what you can do with WIX! Get those extra profits and PLUS sales. Ask your Jobber, or write us direct - TODAY!

Now! Modernize pre-'57 Ford, Lincoln and Mercury PLUS Buick, Oldsmobile and Pontiac

WIX Conversions replace these old-style, full-flow filters in jig time—adapt these vehicles to use WIX "SPIN-ON" Filter. WF-15 for Ford, Lincoln, Mercury; K-40 for Buick, Oldsmobile, Pontiac.



OIL FILTERS AIR FILTERS

WIX CORPORATION . GASTONIA . N. C.

In Canada: Wix Accessories Corp. Ltd., Toronto



NEW!

Ory Type Air filter Cartridges for 1957carsso equipped. Exclusive POLYMITE filtrant for maximum clean air flow. cab-to-axle dimension advantageous for certain trailer operations. (2) three cab-chassis models in the 60 series with 124-in, cab-to-axle dimension to permit bodies chassis with 8, 10 or 12-ft van-type bodies on 104, 125 and 137-in. wheelbases.

Cargo space in these new

vans is 276.45, 334.21 and 392.1 cu ft, respectively. GW ratings are from 5600 to 10,000 lb, depending on tire, spring, and axle options.

"Workmaster" Engine

The 348-cu in. "Workmaster" engine-rated at 335 lb ft of torque at 2800 rpm, 230 bhp at 4400 rpm - is entirely new. With the exception of some minor items, its components are not interchangeable with either the 283 or the 322-cu in. V-8 engines.

Chief among the design features of this engine are a new cylinder block and head. The complete combustion chamber is located wholly within the cylinder bore. Top face of the block is machined at a 74 deg angle to the centerline of the bore instead of the conventional 90 deg, inclining the head more toward the horizontal. Thus the top of the cylinder is elliptical rather than round, making more space for larger valves, central location of the spark plug and staggered valve arrangement.

Aluminum Pistons

"Peaked roof" aluminum pistons are positioned with one dome surface parallel to the plane of the flat head and the other at a 32 deg angle to it. The result is a thin squish and quench area in one-half the cylinder and a wedge-shaped combustion chamber in the other. The arrangement is said to (1) induce extreme turbulence in the fuel-air mixture and (2) together with the short flame travel from the centrally located spark plug, induce high efficiency of combustion.

Exhaust valves are sodiumcooled, Stellite-faced, are used with replaceable Silichrome valve seat insets on the cylinder heads. They are equipped with valve rotators of "Rotocoil" design. Intake valves are aluminum coated.

Camshaft drive is by means of a roller chain. Valve springs are equipped with dampers and hydraulic valve lifters are standard. Pressed steel rocker arms are mounted on individual studs, while pushrods are hollow to provide for lubrication.



Trucks UP TO 10 TONS!

Sliding and Revolving solid Spindle - 3" Diameter . . . cuts set-up time.

12" Spindle travel gives easier access to drum interior.

Multiple speeds and independent feeds. 1 HP Motor.

Turns AND Wet Grinds, SIMULTANEOUSLY, with Vapo-Jet WET Grinder attachment.

There are 2 certain ways to make steady, big profits in today's great demand for Brake Drum Reconditioning! 1) Put this new, medium priced Lathe to work for YOU! Or, 2) take your Brake Drum work to a VAN NORMAN Jobber's Shop that is equipped to turn out these jobs quickly and inexpensively for you. This great, new No. 304 Lathe provides the precision, mirror finish that means maximum life to linings.

An easy, "Pay-as-You-Profit Plan" will put this medium priced Lathe to work for you. Ask your Jobber about the new Heavy Duty No. 304, or write us and we'll tell you where you can get Precision Machining Brake Drum service - from a Shop near you. Van Norman Automotive Equipment Company, Springfield 7, Mass. A Division of Van Norman Industries, Inc.

MACHINING

AN IN MODERN, EFFICIENT SHOPS—EVERYWHERE!



PROVIDES Cushioned Protection FOR EVERY TYPE OF HOOK-UP



FRONT END PICK-UP showing hooks attached to lower suspension arms. NOTE how car is cradled in fabric straps which conform to various contours and spread the load over a large area so as not to damage light grills or panels.



REAR END PICK-UP with short spurs inserted into holes in longitudinal structural members. NOTE this hook-up can be made easily from side without crawling under car.



REAR END PICK-UP with hooks attached to axle. NOTE chains are of ample length to reach any axle. The telescopic "V" type bars properly space car from tow truck and afford a sharp turning radius.



The HOLMES Sling is furnished with spacer bars, lifting straps and two (2) sets of chains with four (4) different hook attachments. It is adaptable to most wreckers, easy to install, profitable to use. Write factory for details on the New HOLMES Sling for safer handling of your customers' cars.

ERNEST HOLMES COMPANY

Chattanooga 7,

.

ennessee

modification of the ventilating system. An alteration of the accelerator pump system is designed to increase six-cylinder economy.

Ford's heavy duty trucks will carry new, heavier transmissions. Medium weight models will offer an optional automatic transmission with improved retarding ability at higher speeds. The handy pickup truck will wear the Styleside box, which matches the cab in width and offers 25 per cent more payload capacity.

Examining the heavier series, Ford will offer a wide choice of

auxiliary fuel tanks at option. If carried, the tanks will increase fuel volume to 120 gal. The new tanks have submerged electric fuel pumps which are said to minimize the hazard of vapor lock.

Heavier new axles

New front axles, heavier, are offered this year at option. A high capacity, rear tandem axle is also offered optional for Ford's 1700 series. The axle provides models with a 32,000 gross vehicle weight rating. Another 1958 addition is a 40 amp generator which is installed on trucks of the 750, 800 and 900 series. Medium and heavy duty models will use new, larger brakes.

Ford will also offer a new triple-drive range automatic transmission for medium and heavy duty models. New extraheavy duty transmissions are available for tandem trucks, for which heavier duty transmissions are also offered. An eightspeed transmission is ready for heavy and extra-heavy duty models.

For highway visibility, electric windshield wipers will accompany all eight cylinder engines. Six cylinder models will have dual vacuum, positive action wipers. All air wipers will be part of air brake - equipped trucks.







Replacement market for ball joints is expanding rapidly

placement market for this new product is expanding rapidly.

Ball joint suspension first appeared on new cars in 1954. Ten new car models featured this suspension in 1957, and the number is expected to increase in 1958. And for good reason! Ball joints help cars hug the road, make steering easier and safer, aid advanced styling.

Today the replacement market for this revolutionary new product is growing by leaps and bounds. Toledo Steel, a leading chassis parts supplier for more than 50 years, offers you a complete line of identical ball joints for the replacement market. Be sure your stock is adequate now!



TOLEDO STEEL PRODUCTS

Division of Thompson Products, Inc.

8482 CEDAR AVE. - CLEVELAND 3. OHIO

er-balance spring, can cause serious injury if the motor assembly is removed without locking the regulator sector in position.

Drill a 1/4" hole through the back plate and regulator sector indicated by "A," "B" or "C" in Fig. 1, depending on the po-

sition of the lift arm.

Be especially careful not to drill through the motor housing.

Insert a 3/16" bolt through the hole and install a nut on the bolt, but do not tighten the nut. Take out the bolts "D" in Fig. 1 that secure the motor to the back plate and remove the motor from the regulator. [See page 62.]

To install the motor, place the motor in position on the back plate and move the lift arms up or down so that the motor pinion gear will mesh with the teeth on the regulator sector, then replace the motor attaching bolts.

Be sure to remove the temporary nut and bolt from the regulator after the motor has been installed.

Replace Door Window Regulator

Carefully work the regulator assembly into place through the rear access hole, then install the regulator attaching screws. Place the inner panel cam on the regulator arm and attach the cam to the inner panel. (On front doors replace the ventilator division channel adjusting stud and nut.) Connect the wiring harness, then lower the glass and replace the lower sash channel screws.

Before going any further, connect the battery and turn on the ignition, then place a jumper across the terminal block to check and correct the operation of the window for alignment.

After adjustments have been made, replace the access hole covers, set the trim panel in place and connect the control switch to the terminal block. then fasten the trim panel to the door. Replace the inside door handle and garnish moulding and check the operation of the window once again.

On Chrysler and Packard cars to remove door window lifts, here is the pattern: Lower the window and disconnect the battery, then remove the garnish moulding, inside door handle and arm rest. Pry the trim panel away from the door, disconnect the wires or terminal block from the control switch and remove the trim panel. Disconnect the wires from the lift motor, then detach the window lift arms from the lower sash channel. Now

(Continued on page 86)



C. E. NIEHOFF & CO.

4925 LAWRENCE AVENUE . CHICAGO 30, ILLINOIS

WAREHOUSES: ATLANTA 3, GA., 95 Pine St., N. E. • BOSTON 34, MASS., 250 Brighton Ave. • DALLAS, TEX., 2715 Main Street • NEW YORK 19, N. Y., 250 W. 54th Street • PHILADELPHIA, PA., 1800 Fairmont Avenue BRANCH: LOS ANGELES 15, CAL., 1330 W. Olympic Blvd.



"Who's got time to write ads? We're too busy writing orders!"

-says Bernard O'Daniel, President, Key Motors, Inc., Evansville, Ind.

"Response to our new 1958 De Soto has been terrific," says Mr. O'Daniel, "from the Fireflite all the way down to our new, moppet-sized Firemite, the hottest promotion tool I've seen in 22 years selling cars. We had six thousand people visit our showroom in the first four days alone . . . and we've been busy writing orders ever since!"

Bernie O'Daniel is typical of the smart,

aggressive, promotion-minded De Soto dealers who are discovering that a De Soto franchise is worth more in '58 than ever before. His 1958 De Soto line is the engineering and styling leader, with prices covering the entire medium-price field. He has the support of strong national advertising, backed by a year-long program of hard-hitting selling promotions. And he's working with it—making the most of it!



BERNIE O'DANIEL says . . . "Look to the future . . . IT PAYS TO BE A DE SOTO DEALER!"

raise the glass and prop it in the upper position, then remove the window regulator to door attaching screws and the pivot guide retaining pin. Lower the motor and regulator assembly and work it out through the opening in the door.

The window lift motor may be replaced without removing the regulator assembly. Remove the trim pad, disconnect the wires from the motor, remove the nuts holding the motor to the gear box and pull the motor down and away from the shaft.

Replace the motor in the reverse order of removal.

Caution: Note the position of the regulator gear and the counter-balance spring. With a large pair of pliers carefully remove the spring before attempting to remove the gear box. Due to the tension of the spring serious injury may result if this precaution is not taken.

After the spring has been removed, take out the screws holding the gear box to the regulator and remove the gear box. Then remove the nuts holding the motor to the gear box and pull the motor away from the shaft.

To install the gear box, mount it on the regulator so that the gear box pinion meshes with the regulator gear, then replace the gear box screws and the counterbalance spring. Install the motor on the shaft and replace the motor mounting nuts.

Place the motor and regulator assembly through the opening in the door and insert the pivot arm pin into the guide, there is no clip, then install the regulator attaching screws, finger tight. Make certain the pivot arm pin did not slip out of the guide, then insert and secure the control arms into the lower sash channel. Connect the wires to the motor and connect the battery, then using a jumper across

the terminal block check and correct the operation of the window for alignment.

After adjustments have been made, set the trim panel in place and connect the control switch to the wires or terminal block, then fasten the trim panel to the door. Replace the arm rest, inside door handle and garnish moulding and check the operation of the window once again.

Ford Motor Co.

Two types of electric regulator assemblies, "A" (Fig. 3) and "B" (Fig. 2), were installed in 1952 to 1954 Ford Motor Company cars. The two assemblies are interchangeable but the installation of type "A" is different than the installation of type "B." The arm and plate is not an integral part of type "A" but is an integral part of type "B."

remove door window regulator on Type "A": Lower the window and disconnect the battery, then remove the hardware, garnish moulding and trim panel and disconnect wires from the control switch. Remove the clip that attaches the arm and plate to the regulator (Fig. 3), then remove the cap screws that secure the regulator to the inner door panel. Lower the assembly and remove it through the access hole. Remove the cover plate with the relay attached and disconnect the wires from the motor to the relay.

To remove the arm and plate assembly, detach the arms from the rollers, then raise the window and prop it in the upper position. Remove the cap screws that secure the arm and plate assembly to the inner door panel, then slide the assembly forward to release the roller from the guide on the inner door panel. Lower the assembly and remove it through the access hole.

To replace motor and bracket support assembly on Type "A" (see Fig. 3), clamp the window regulator assembly in a vise and unload the counter-balance spring by pulling the hooked end up and over the stop. Remove the three screws that hold the motor and bracket support to the regulator and remove the motor. Take off the cover and shaft from the motor and bracket support, then remove the coupling, pinion and shield assembly from the regulator.

To install, assemble the coupling, pinion and shield assembly, then position and install the cover and shaft to the motor and support bracket. Place the motor and support bracket on the regulator and install the three screws, then load the counter-balance spring.

To replace door window regulator, Type "A," raise the regulator assembly into position in the door panel and install the retaining screws, but do not tighten them until adjustments are made. Connect the wires from the motor to the relay and install the plate with the relay attached, to the door.

To replace the arm and plate assembly, lower the window and assemble the rollers in the glass channel, then raise the arm and plate assembly and start the roller on the guide. Install the retaining screws but do not tighten them. Connect the regulator link to the arm and plate assembly and install the clip. Lubricate all rollers and guides. then connect the battery. Place a jumper across the control switch wires and check and adjust the alignment of the window, then tighten the regulator screws and the arm and plate screws. Connect the control switch wires and replace the trim panel and hardware.

To remove door window regulator, Type "B," lower the window and disconnect the battery, then remove the hardware,

garnish moulding and trim panel and disconnect the wires from the control switch. Detach the arms from the rollers on the glass channel, then raise the window and prop it in the upper position. Remove the cap screws that hold the regulator assembly to the inner door panel, then slide the assembly forward to release the roller from the guide on the inner door panel. Lower the assembly and remove it through the access hole. Remove the cover plate with the relay attached and disconnect the wires from the motor to the relav.

To replace motor assembly and coupling. Type "B," disconnect the battery, then remove the hardware, garnish moulding and trim panel and disconnect the wires from the control switch. Remove the two nuts and washers which hold the motor to the window regulator assembly, pull the motor and rubber drive coupling away from the regulator, then out through the access hole. Remove the cover plate with the relay attached and disconnect the wires from the motor to the relay.

To install, attach the rubber coupling to the drive shaft and insert the motor and coupling through the access hole. Slide the rubber coupling over the drive assembly pinion, line up the motor attaching studs to the regulator and install and tighten the nuts. Connect the wires from the motor to the relay and secure the relay and cover to the door. Connect the wires to the control switch, then replace the trim panel, hardware and garnish moulding and connect the battery.


Clamp the window regulator assembly in a vise and unload the counter-balance spring by pulling the hooked end up and over the stop. Remove the screws that hold the drive assembly to the regulator and pull the drive pinion out of the rubber coupling.

To install, place the drive assembly on the regulator, slide the drive pinion into the rubber coupling and replace the screws, then load the counter-balance spring.

To replace door window regulator, Type "B," lower the window and assemble the rollers in the glass channel, then raise the regulator assembly and start the roller on the guide. Install

the regulator retaining screws, then connect the wires from the motor to the relay and secure the relay and cover to the door. Connect the battery, then place a jumper across the control switch wires and check and adjust the alignment of the window. Connect the control switch wires and replace the trim panel and hardware.

(Part II continued next month)



McRill says: "My Inland-equipped radiator dept. gave me an additional \$12,416 in 1955—over \$16,000 in 1956! My total repair volume is up 41%, due largely to added business attracted by my radiator dept. To Inland equipment and training goes much of the credit!"

YOU CAN DO AS WELL! Many others, with modern Inland equipment, are making \$8,000, \$10,000, \$15,000 a year! Car owners are now aware it pays to have their radiators cleaned and repaired regularly.

INLAND NATIONAL ADVERTISING HELPS YOU! Inland ads in the Post and Life warn car owners of the danger of neglecting radiators...urge regular servicing...suggest seeking the nearest shop displaying the Inland sign. Inland, world's largest radiator servicing equipment manufacturer, offers the complete package — equipment, training, merchandising, even a "Pays-For-Itself" purchase plan. Mail the coupon for free descriptive book.

FREE TRAINING Complete factory school trains you or your man quickly. Cleaning, repairing, recoring, pricing, merchandising—everything! Hundreds of graduates now expert radiator repairmen. It's FREE to Inland lent training!" says Moser Motor Sales, Berne, Ind.,

MAIL TODAY

New free 48-page book, "Blueprint for Profits," tells about many making an EXTRA \$8,000 to \$15,000 a year servicing radiators. Complete with illustrations, descriptions and prices of required equipment. Popular "Pays-For-Itself" purchase plan. Invest a minute to mail the coupon—the rewards can be amazing! Send today!

INLAND MFG. CO., 1108 Jackson St., Dept. MA-12, Omeka 2, Nebr.

"SOLD EXCLUSIVELY BY MAIL"

	_						
							, Omaha 2, Nebr.
PI	ease	send	new	free	book,	"Blueprint	for Profits."

FIRM (PLEASE PRINT)

ADDRESS.

CITY______ZONE_STATE____

If dealer, make of car sold.

Are you now operating a radiator dept.?

Yes
No

Horsepower Continued from page 49

package; the Chrysler 300C is 390-bhp with fuel injection and 380-bhp with an 8-barrel carburetor; and Lincoln is rated 375-bhp with a standard 4-barrel carburetor.

However, the arrangement of engines in the tabulation is based not upon maximum output but according to the ratio of Bhp/cu-in. As shown, the first five places in the tabulation are as follows: No. 1 — Corvette with fuel injection and special camshaft; No. 2 and 3 to the Chrysler 300C; No. 4—Golden Hawk with McCulloch supercharger; and No. 5 — Lincoln

and Mercury with 6-barrel carburetion.

This year all makes have improved the ratio of Torque/cu.in. displacement. The four top ratings are as follows: Edsel—1.158; Lincoln—1.139; Chrysler Division—354 cu.in. engine—1.144 and the 392 cu.in. engine—1.147. The other engines, however, are quite comparable within small percentage points.

From the standpoint of bore/stroke ratio, the trend has been to shorter stroke and much larger bore. The only exceptions are the three engines which have not changed physically this year. The Dodge Royal—0.97; Golden Hawk and President—0.98. All the rest are oversquare, the top ratios being — Mercury with 1.30; and Chevrolet with 1.29. This trend, coupled with suitable rear axle ratios accounts for lower engine speeds for a given road speed.

Compression ratio, with only a few exceptions touches 10 to 1 with maximum rating of 10.5 to 1 on a number of makes. Obviously, compression ratio must inch upwards to stay within the bounds of the octane ratings of fuels.

Figures may not lie, but some get snarled up in statistics.

Pressure Cap . . .

(Continued from page 41)

exposed. Faulty head gaskets, leaking radiator cores, leaking heater hose connections are also revealed. In short, the pressure tester is an excellent Sherlock Holmes to solve cooling system problems!

(The editors acknowledge with appreciation the contributing data furnished for this article by Mr. Glen A. Johnson, Stant Mfg. Co. engineer, Connersville, Ind.)





ONE

HANDY TOOL

ADJUSTS POINTS

and CARBURETORS!



For Adjusting Delco-Remy Distributors and Carburetor Idle Mixture Screws

XCELITE'S done it many times before, and we'll be doing it many times again. There was a new automotive service job to be done, so we designed a new tool—to do it quicker, easier, better.

The XCELITE No. 112 Unit features a quick-change chuck at the working end of its flaxible shaft. With the hooded screwdriver bit in the chuck, it's easy to adjust the carburetor idle mixture screw. A quick change to the Allen bit and you're ready to adjust Delco-Remy Distributors.

The flexible shaft saves time by letting you get into those "hard-to-reach" places. The chuck, plus the flexible shaft, saves you the added expense of stocking several bits of different lengths. Extra bits are available at low cost to fit larger screw sizes.

And, along with all these brand-new time-saving, moneysaving features . . . you get the old, reliable XCELITE quality, dependability and a long life of trouble-free service.

ORDER THE XCELITE NO. 112 NOW FROM YOUR DEALER!

XCELITE, INC.

Dept. K

Orchard Park, N. Y.

in Canada — Charles W. Pointon, Ltd., & Alsina Ave., Toronto, Ont. For Originality

7 REASONS WHY



Should Be A "MUST" In All Automotive Painting Operations!

- NO DRYING TIME NEEDED! This sealer and primer requires none! The finish coat of synthetic ename! is sprayed immediately over the coat of X-I-M FLASH BOND!
- 2 NO SANDING RE-QUIRED! It saves you sanding and tacking off time between the primer coat and the finish coat!
- PROVIDES OUTSTAND-ING ADHESION when a used over all painted surfaces that are chemically clean—with little or no sanding necessary!
- SEALS MOST "BLEED-ERS"! Stops color costs from soaking into spots that have weathered or are worn! Small bare metal spots need not be filled!
- 5. ACTS AS A RUST IN-HIBITOR when applied over slightly rusted surfaces, or over surfaces where loose rust and scale has been removed.
- IMPARTS FLEXIBILITY
 to finish coats and resistance to weathering!
 Thus resists damage to
 finish due to sudden
 weather changes and unusual outdoor conditions!
 Helps to resist dulling,
 chipping, peeling and flaking!
- GIVES EXCELLENT ADHESION for your finish coat when used over Aluminum, Stainless Steel, Chrome Plate, Magnesium, Brass, Copper, Electrolytic Galvanized Surfaces, Steel and Iron 1

CHECK ALL SEVEN! ADD THEM UP!

You will find the answer is a quality finish—A finish that will stay bright and have that "Like New Look" longer—At a decided savings in money, time and labor to you!

Proven in the field for more than 20 years! Get X-I-M Flash Bond from your dealer or send coupen teday!



City.

H. FORSBERG CO.,

MA-6

5103 Lakeside Ave., Cleveland 14, Ohio

- Send complete information on X-1-M FLASH BOND.
- Ship us one gallon via parcel post and invoice through our supply house. (Give name of supply house below.)

Street		A COLUMN TO THE PROPERTY OF THE PARTY OF THE	
City	Zone	State	ionimo

Zone State

Oklahoma School Teaching Diesel

"More testing and less guessing" is Frank Tozer's formula for success. Tozer is a specialist in starting machines. It is his job to teach Diesel students at Oklahoma A. & M. Tech, Okmulgee, the proper method of getting engines started.

He's taught over 111 classes.

Students can and do test every unit of the car or truck engine. All units with the exception of the carburetor can be tested without being put on the engine. The carburetor must be put on the engine before it can be tested.

There are 11 engines in the Diesel shop, parts of which students and instructors have disassembled and reassembled over 100 times. That is part of the task of keeping the machines running.

In a "dry" run the student may be told that a unit is bad. He must disassemble the unit, test each part, then when it is all apart and has been tested, he is told to assume that he has all new parts and to reassemble it.

National A. M. A.

Lane J. Walker, of Peoria, Ill., has been appointed to the 3rd vice presidency of the National Automotive Maintenance Association. Announcement of the successor to L. C. Kater in this post was made by C. A. Fox, president. Mr. Kater had resigned because of press of business.


Sports Car Racing Receives Boost

The American Oil Company has entered into an agreement with the Lime Rock Corp., Conn., for the support of sports car racing and safety development at northwestern Connecticut's new race circuit.

As its initial step, Amoco awarded a gold trophy to the winner of the "Little Le Mans" 10-hour endurance race for small production cars, October 12.

The track at Lime Rock will also serve as an outdoor laboratory for Cornell University's highway safety tests.

For Automatic Transmission Parts



The Largest, Most Complete Line in the Business!

Now...a single source for ALL your automatic transmission parts needs, for ALL MAKES OF TRANSMISSIONS. Bushings, plates, gaskets, sealings rings, the basic hard parts...LEMPCO

supplies them *all*, in quality guaranteed to equal or surpass original equipment specifications. Save time, save work . . . see your Lempco jobber, or write us for his name.

...Tell Your Jobber You Want...



© 1957 Lempco Automotive, Inc.

2953 EAST 55th STREET . CLEVELAND 27, OHIO



get All the BEAR FACTS and you'll buy a BEAR. On A Car Balancer



ONLY BEAR

with the SPEEDIE Adapter has the FASTEST accurate centering! It always goes on right the first time because it uses the truest part of the wheel...the spindle center. ONLY BEAR

balances on the HOIST or FLOOR with equal ease, speed and safety! Limited space need not keep you from getting in on BIG BALANCING MONEY! Spinner fits easily on rack.

ONLY BEAR

gives you such superior balancing control! Just 2 knobs to use! Tells you if you're adding or taking away weight while wheel is spinning... Balance Prover tells when you're through!

Compare Fact for Fact...See for Yourself Why You Can Make More, Do More with BEAR On-A-Car!

ONLY BEAR

lets you sit while balancing...
no squatting or stooping! It's the most
convenient, safest arrangement: you
work from the side, spin from the front.
Closely simulates driving conditions.

ONLY BEAR

has the Balance Prover! Nothing like it to dramatize the need for balancing! A real sales clincher...shows customers just how badly wheels are out of balance.

ONLY BEAR

brings you all these ease-ofoperation features in an On-The-Truck Balancer, too! Handles all types of Buddtype wheels, cast-spoke types or light truck wheels.



Chilton's MOTOR AGE, DECEMBER, 1957


... nothing extra to install! Get all the Bear Facts and a FREE DEMONSTRATION from your Jobber or write:

Bear Mfg. Co., Dept. M-1, Rock Island, Illinois

Change Truck Tires EASIER with

KEN-TOOL
OUALITY BEAD LOOSENERS

Free frozen beads quickly with exclusive Ken-Tool Bead Looseners. They provide greater leverage . . . loosen the most stubborn truck tire beads quickly, easily.



SEE YOUR JOBBER on the complete line of Job-Designed Ken-Tools. Forged by the largest exclusive manufacturer of top-quality Tire-changing Tools and Equipment. THE KEN-TOOL MFG. CO., AKRON 5, OHIO.

(Superior Design)





for dry, safe, tidy floors

New, green-flecked Sol-Speedi-Dri floor absorbent does more . . . does it better. Absorbs—thirsty for oils, greases, liquids. Batales—picks up more . . . holds more. Cewars—goes further than ever. Resists—won't cake, mat, break up, or get "mushy." Destlessness—most dust-free you can buy. Belform—bag after bag, ton after ton. For sample, see your local jobber, or write Speedi-Dri Div., Minerals & Chemicals Corp. of America, Essex

Turnpike, Menlo Park, N. J.



Calendar Of Coming Events

Dealers Conventions

Jan. 11-15, 1958—National Automobile Dealers Assn., Miami Beach.

Feb. 23-24 — Louisiana Automobile Dealers Assn., Inc., Roosevelt Hotel, New Orleans.

Apr. 10-11—Illinois Automotive Trade Assn., Springfield, Ill.

May 5-7—Joint Convention, Washington State Automobile Dealers Assn. and the Motor Dealers Assn. of British Columbia, Empress Hotel, Victoria, B. C.

May 11-13—Idaho Automobile Dealers Assn., Lewiston, Idaho.

May 11-14—36th annual convention, Automotive Engine Rebuilders Assn., Sheraton-Park Hotel, Washington, D. C.

May 12-13 — Pennsylvania Automotive Assn., Haddon Hall Hotel, Atlantic City, N. J.

June 8-9—Automobile Dealers Assn. of Indiana, Mirott Hotel, Indianapolis.

Sept. 14-16 — Michigan Automobile Dealers Assn. Pantlind Hotel, Grand Rapids.

Automobile Shows

Dec. 14-19—Miami Automobile Show, Dinner Key Auditorium, Miami.

Jan. 3-11, 1958—Upper Midwest Auto Show, Municipal Auditorium, Minneapolis.

Jan. 4-11—Buffalo Auto Show, Masten Avenue Armory, Buffalo.

Jan. 4-12—Chicago Auto Show, International Amphitheatre, Chicago.

Jan. 4-12—National Automobile Show, New York Coliseum.

Jan. 11-19—National Capital Area Auto Show, D. C. National Guard Armory, Washington.

Jan. 17-24—San Antonio Auto Show, Bexar County Coliseum, San Antonio.

Jan. 17-25—Indianapolis Automobile Show, Manufacturers Bldg., State Fair Grounds, Indianapolis.

Jan. 18-25 — Pittsburgh Automobile Show, Hunt National Guard Armory, Pittsburgh, Pa.

Jan. 18-26 — Cincinnati Auto Show, North and South Wings, Music Hall, Cincinnati.

Jan. 18-26—Detroit Auto Show, Artillery Armory, Detroit.

Jan. 22-25—Huntington Automobile Show, Memorial Field House, Huntington, W. Va.

Jan. 23-28—Tampa Auto Show, Fort Hesterly Armory, Tampa.

Hesterly Armory, Tampa.

Jan. 25-Feb. 2—Houston Automobile

Show, Houston.
Feb. 1-8—Rochester Auto Show, War Memorial Exhibit Hall, Rochester, N. Y.

Feb. 1-9—Louisville Automobile Show, State Fair Center, Louisville.

Feb. 8-16—Milwaukee Auto Show, Milwaukee.

Feb. 10-15—Denver Automobile Show, Denver Coliseum, Denver.

Feb. 15-24 — Columbus Automobile Show, Franklin County Veterans Memorial Bldg., Columbus, Ohio. Feb. 16-22—Syracuse Auto Show, Syracuse, N. Y.

Feb. 19-23—8th Annual National Autorama, Conn. State Armory, Hartford, Conn.

Feb. 21-23—Cheyenne Auto Show, Frontier Pavilion, Cheyenne.

Mar. 1-9—Kansas City Auto Show, Municipal Auditorium, Kansas City, Mo.

Apr. 5-13—International Auto Show, New York Coliseum, New York.

General

Nov. 30-Dec. 1—Florida Automotive Wholesalers Association annual convention, Orlando, Fla.

Dec. 5-6—American Petroleum Institute Oil Information Committee meeting, Biltmore Hotel, New York City.

Dec. 10—Annual Dinner, Philadelphia Automobile Trade Assn., Philadelphia.

Jan. 13-17, 1958—Annual Meeting, Society of Automotive Engineers, Sheraton-Cadillae and Statler Hotels, Detroit.

Feb. 3-6—31st Annual National Automotive Accessories Manufacturers' Exposition, Navy Pier, Chicago.

Feb. 12-14—American Petroleum Institute Div. of Marketing, Marketing Research Committee, Biltmore Hotel, New York City.

Feb. 18-19 — Motor & Equipment Wholesalers Association convention, Statler Hotel, Los Angeles.

(Continued on page 93)

Classified Advertisements

Club forming for all types motor vehicles, except Big Three. IMVOW, Albion, N. Y.

Offering distributors foreign car parts. Eagle Sales Company, 2779 N.W. 37th Street, Miami 42, Florida.

\$1000.00 a month selling automotive shelving—parts bins—counters—gasket and tail pipe racks—shop equipment. Terrific commissions. Free 32-page catalog—jobber discounts. Write today! BERNARD FRANKLIN CORP., Hedley & Bath Sts., Dept. 58E, Phila. 37, Pa.

AUSCO...

Manufacturers of Quality Jacks for Every Service Need!

AUTO SPECIALTIES Mfg.Co., Inc.

Calendar . . .

Continued from Page 92

Feb. 18-19—National Standard Parts Association convention, Ambassador Hotel, Los Angeles.

Feb. 27-28—American Petroleum Institute Div. of Marketing, Lubrication Committee meeting, Sheraton-Cadillac Hotel, Detroit.

May 21-23—American Petroleum Institute Div. of Marketing, midyear meeting, Roosevelt Hotel, New Orleans.

Aug. 17—21st All-American Soap Box Derby, Akron, Ohio.

NADA Chairman Post to Dahlem

Earle C. Dahlem, vice president and general manager of Wm. L. Hughson Co., San Francisco Ford dealer, has been appointed Area Chairman for the National Automobile Dealers Association. According to Frederick M. Sutter, president of

NADA, Mr. Dahlem will be responsible for reporting on the affairs of the national association to other franchised dealers in his region. He is also in charge of recruitment of new members.

Mr. Dahlem was appointed jointly by Sutter and officials of the Northern California Motor Car Dealers Association. His appointment is effective until June 30, 1958.

The PIONEER Tool FOR INSTALLING VALVE SEAT RINGS



THE FIRST... and still the MOST POPULAR, MOST PRACTICAL, SIMPLEST, MOST UNIVERSAL tool of its kind made. EVERLASTING... the first tools made over 25 years ago are still in service.

K. O. LEE COMPANY
ABERDEEN, SOUTH DAKOTA

Faster Edging of

AUTO GLASS

Plus 60% Increase in Belt Life . . .

"SOMACA" No. 106-FB12RP 106" WET ABRASIVE BELT MACHINE WITH "CONTACT RUBBER ROLLER PLATEN"

Standard of the Glass Shop Trade

THOUSANDS IN USE

The sensational new Contact Rubber Roller Platen on the ever popular Somaca Wet Abrasive Belt Machine makes a combination hard to beat.

Start saving TIME and MONEY now—write for complete information and prices.



SOMMER & MACA Glass Machinery Co.

3624 SOUTH OAKLEY AVENUE CHICAGO 9, ILLINOIS

THOR PORTABLE POWER TOOLS

1500 tools for automotive service, industry, construction

TOOLS

World's largest exclusive manufacturer of portable air and electric tools

THOR POWER TOOL COMPANY

Prudential Plaza, Chicago 1, III.

Branches in all principal cities

SPECIAL WIRE BRUSHES? THEY'RE STANDARD AT RIMAC!



There's a "Rimac-right" brush in stock mated to every special cleaning job . . . Wheel, rotary or hand types — in cable twist, spiral or straight strands.

Illustrated, is popular interchangeable valve guide brush. Ask your jobber or write for literature.

RINCK-MCILWAINE, INC.

A	TI	Q
AC Spark Plug (Electronics Div.)	1 Index to	Quaker State Oil Refining Corp
American Chain & Cable Co.,	10 Advantigan	~
Auto Specialties Mfg. Co	92 Adveruser	S R
		Ramsey Corp3rd Cover
B Bear Mfg. Co	This Advertisers' Index is published as a convenient and not as part of the advertising contract. E one will be taken to ladex correctly. He all	Rochester Products Div 4
	ance will be made for errors or failure to las	
C		S
	79	Schrader's Son Div., A 73
Champion de Arment Tool Co.		Sealed Power Corp2nd Cover
Champion Spark Plug Co	0-9	Snap-on Tools Corp 77
Chrysler Corp. De Soto Div	85	Sommer & Maca Glass Ma- chinery Co
Parts Div	11	Speedi-Dri Corp 92
Classified Advertisements	92	Standard Motor Products, Inc. 2
Commercial Credit Corp	5	Stant Mfg. Co 82
D		Steward-Warner Corp. Instrument Div
Delco-Remy Div14	1-15 I	
De Soto Div	85 Ingersoll-Rand	75 T
Ditzler Color Div	95 Inland Mfg. Co	87
Du Pont de Nemours, Inc. Refinishes Div	7	Texas Co
		78 Thompson Products, Inc. Service Sales Div
E		Thor Power Tool Co 93
Echlin Mfg. Co	71 K	Timken Roller Bearing Co 28
	Ken Tool Mfg. Co	92 Toledo Steel Products Div 83
F	Kendall Refining Co	76
Federal-Mogul-Bower Bear-		v
ings, Inc.	L	
Federal-Mogul Service Div.	6 Lee Co., K. O	Van Norman Automotive Equipment Co 80
National Seal Div	21 Lempco Automotive Inc	90
Forsberg Co., H	89	
	N	W
G	National Seal Div	21 Wagner Electric Corp 26-27
G Globe Hoist Co	National Seal Div	21 Wagner Electric Corp 26-27 84 Weaver Mfg. Co
	29 Niehoff & Co., C. E	84 Weaver Mfg. Co17 thru 20
Globe Hoist Co	29 Niehoff & Co., C. E	84 Weaver Mfg. Co17 thru 20 Wilkening Mfg. Co32 Wix Corp
Globe Hoist Co	29 Niehoff & Co., C. E	84 Weaver Mfg. Co17 thru 20 Wilkening Mfg. Co 32

Ditzler offers you 2 GREAT PRIMER SURFACERS in 6 colors for every refinishing need!



They're Better 7 Ways!

- Saves you money! High solid content gives more filmforming materials. Fewer coats needed. Free from shrinkage.
- 2. Saves you labor! Easy sanding—requires less work to get a smooth surface. Water sands with 320 paper and dry sands with 360. No clogging of paper.
- 3. Gives you first class appearance! Excellent hold-out of lacquer or enamel colors over Rip Rap or San Quic produces an outstanding job with maximum gloss of final finish.
- You get superior performance! No splitting or chipping around the feather edge. Feathers out beautifully to a mere shadow.
- 5. Your jobs will stand up longer! Detroit and Florida exposure tests show Ditzler's superiority in durability under the most severe weather conditions.
- 6. Saves you time! Famous for non-settling. No time wasted in laborious stirring. Stirs easily even after thinned material has stood for hours in gun cup. Does not settle hard in can.
- 7. Handles easily! Convenient easy-to-pour cans. Oblong type with LARGE opening—no waste in pouring.
- Ask your local Ditzler jobber for these outstanding undercoaters and see for yourself how much better they are.

Ditzler Color Division, Pittsburgh Plate Glass Company, Detroit 4, Michigan



DITZLER

PAINTS . GLASS . CHEMICALS . BRUSHES . PLASTICS . FIBER GLASS

PITTSBURGH PLATE GLASS COMPANY

IN CANADA: CANADIAN PITTSBURGH INDUSTRIES LIMITED



She had begged her husband for months to have his picture taken. last he made the appointment with the photographer. When the proofs arrived, his wife exclaimed in horror. "Oh, there's only one button on your coat!"

"Thank heavens," he said, "you've noticed it at last."

An Indian petitioned a judge of a Montana court to give him a shorter name. "What is your name now?" asked the judge. "Chief Screeching Train Whistle,"

said the Indian.
"And to what do you wish to shorten it?"

The Indian folded his arms majestically and grunted, "Toots."

One married man: "I'm very happy. I have a wonderful home, a good job, and the finest wife in the country."

Another man: "Who wouldn't be

happy with his wife in the country?"



"Yeah, sales are running ahead of 1932 anyhow-

Brown's symptons were alarming enough to make him go to the doctor

for a checkup.

"What does the report show, Doc?"

"According to this analysis," answered the medico, "there is every indication that a small percentage of blood is getting into your alcohol system."

Explorer — "There we were surrounded by natives. They uttered sayage cries and beat the ground with their clubs."

Bored listener-"Golfers probably."

A baseball rookie was proving him-self an all-around nuisance during spring training. He persisted in handing out opinions on every phase of the game and giving unasked advice to the other players. One day he was watching an outfielder at batting prac-tice and noted that the label of the bat was turned toward the pitcher.
"Oh, do you do it that way?" the

rookie asked. "I always hold the bat so I can see the trademark."

"When I come to bat." replied the other evenly, "I come to hit, not to read."

Two men were driving along discus-Two men were driving along discussing the high rate of taxes and the waste of money by the government. At the height of their discussion a school bus passed them from the opposite direction. "See! That's what I was a boy we walked three miles to school and three miles back home each day. Now we spend \$5,000 for a bus to pick up the children so they don't have to walk. Then we spend \$50,000 for a gymnasium so they can get exercise."

Recruit: What's that ugly insignia on the side of that bomber? Corporal: Shh! That's the CO look-

ing out of the cockpit window.

A street sign read, "School—don't kill a child." Beneath was childish scrawl, "Wait for a teacher."

A man isn't henpecked as long as he has a roof over his head and is able to raise it occasionally.




"I'd size him up as a hot prospect for an air-conditioned model."

AUTO LICENSE BUREAU



"By the authority vested in me by this commonwealth, I now pro-nounce you man and car."



Circumferential Expansion Chrome Oil Rings to insure FINEST Get UP and GO! for EVERY Engine!

Not just one exclusive chrome plated oil ring . . . but two! That is Ramco Engineering's answer for you who want finest re-powering results and maximum customer goodwill. Chrome C-9 or Chrome Spiro-Seal, whichever oil ring will deliver finest re-powering results, is the oil ring you get when you use Ramco engineered 10-Up sets.

Each ring has years-ahead features which make it the outstanding performer in the engine for which each is recommended. In C-9, for example, you get Ramco's exclusive Circumferential Expansion construction. This puts up to 20% more contacts on the chrome rails to assure maximum conformability. It also provides ad-

vanced side-sealing action so important for many of today's engines.

In Spiro-Seal Oil Rings, you get the exclusive Ramco Circumferential Expansion action of the Chrome Spiro-Segment for both efficient side sealing and superior conformability. This


plus the Double-Life Principle which utilizes, also, a full fledged, cast-iron oil ring makes it the outstanding performer for most of today's re-ring jobs. For all the facts about Ramco engineered 10-Up piston ring sets, see your Ramco Jobber, or write Ramsey Corporation, St. Louis 8, Mo.

Whatever is FINEST for the Engine you get in

RAMCO

19 piston ring sets

For Power or Standard Brakes



Insist on Thermoid "C-B" Lining

Whether you use bonded shoes or riveted segments, you choose quality and safety when you insist on Thermoid Custom-Built Brake Lining — the one brake lining recommended for both power and standard brakes.

Thermoid, constantly abreast of modern brake requirements, brings you the one lining that's custom-built and certified* for all cars. And you can service 90% of the popular car market—including 1957 models—with just two fast moving assortments of Thermoid Bonded Shoes.

*The only Brake Linings certified by The Pittsburgh Testing Laboratories.



Thermoid Hydraulic Brake Parts and Fluid



Thermoid Company . Trenton, New Jersey

the standard of precision processing in brake lining, brake blocks, hydraulic fluid, cylinder assemblies, hydraulic brake parts